

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator PAN AMERICAN PETROLEUM CORPORATION	8. Farm or Lease Name WINGERD
3. Address of Operator BOX 68, HOBBS, N. M. 88240	9. Well No. 7
4. Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>NORTH</u> LINE AND <u>990</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>24</u> TOWNSHIP <u>12-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat GLADIOLA WOLF CAMP
15. Elevation (Show whether DF, RT, GR, etc.) <u>3877 GL</u>	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Physical P + A operations completed 1-11-68.
Abandoned as follows:

1. Spotted 20 st. cement plug 5175-5100 (Perfs 5104-5170)
2. Shot + pulled 5 7/8" cog @ 4424. 25 st in + out of slab.
3. Cut + pulled 3 7/8" cog @ 924. 25 st in + out of slab.
4. 25 st in + out of 1 3/8" @ 323.
5. 10 st @ surface & erect P + A marker.

Final cleanup will be made and ground restored to contour.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE AREA SUPERINTENDENT DATE 2-26-68

APPROVED BY John W. Runyan
1-NSW
1-1075
1-5050
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____