

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- SALT WATER DISPOSAL WELL		7. Unit Agreement Name
2. Name of Operator Amoco Production Company		8. Farm or Lease Name GLADIOLA WOLF CAMP - DEVONIAN SWD
3. Address of Operator BOX 68, HOBBS, N. M. 88240		9. Well No. 1
4. Location of Well UNIT LETTER P 660 FEET FROM THE SOUTH LINE AND 660 FEET FROM THE EAST LINE, SECTION 24 TOWNSHIP 12-S RANGE 37-E NMPM.		10. Field and Pool, or Wildcat GLADIOLA-WOLF CAMP
15. Elevation (Show whether DF, RT, GR, etc.)		12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The well is no longer suitable for use as a SWD well nor as a producing well. Propose to P & A as follows:
Spot 75.04 from PBD 9770 Back up to cover purps 9412-9636.
Load hole w/ mud.
Shoot and pull 7" from appx. 4500'.
Spot 25.04 cmt plug in: out of 7" stub - if cut near 9 7/8" shoe - cover both points.
25.5x In 9 7/8" shoe @ 9495. Shoot & Pull 9 7/8" from appx 700'.
25.5x In & Out 9 7/8" stub; 50.04 plug in: out of 13 3/8" CSA 323; 10.04 @ surface & erect P & A marker.
Make final cleanup and restore ground to contour.

TD- 9820' 13 3/8" CSA 323' - Circ 7" CSA 9818' w/ 1505x.
PBD- 9770 9 7/8" CSA 2298 - 2 Stage/1505x PERFS- 9412- 9636

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE **AREA SUPERINTENDENT** DATE **APR 27 1971**

APPROVED BY **0+2 NMOC-H** TITLE **SUPERVISOR DISTRICT 1** DATE **APR 29 1971**

CONDITIONS OF APPROVAL, IF ANY:
1- ACJR
1- SUSP
D.D.H.

RECEIVED

APR 20 1971

OIL CONSERVATION COMM.
HOBBS, N. M.