

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
- - - - -	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Skelly Oil Company</b>		8. Lease Name <b>M. A. Foster</b>
3. Address of Operator <b>P. O. Box 1351, Midland, Texas 79701</b>		9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>I</b> <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>27</b> TOWNSHIP <b>12S</b> RANGE <b>37E</b> N.M.P.M.		10. Field and Pool, or Wildcat <b>Gladiola Wolfcamp</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3898' DF</b>		12. County <b>Lea</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:


SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Pull tubing and Reda pump.
- 2) Run tubing open-ended and load hole with 10# mud. Spot 45 sacks of cement at 9525-9875'. Pull tubing.
- 3) Shoot 5-1/2"OD casing at approximately 6700' and pull.
- 4) Shoot 8-5/8"OD casing at approximately 600' and pull.
- 5) Run tubing and spot cement plugs as follows:
  - 25 sacks across stub of 5-1/2"OD casing
  - 25 sacks at 7180-7240'
  - 25 sacks at 6530-6590'
  - 25 sacks at 5900-5960'
  - 25 sacks at 4425-4500'
  - 25 sacks across stub of 8-5/8"OD casing
  - 25 sacks 360-380'
  - 10 sacks in top of 13-3/8"OD casing
- 6) Set marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <b>(Signed) J. E. Avent</b>	TITLE <b>District Adm. Coordinator</b>	DATE <b>May 1, 1970</b>
APPROVED BY 	TITLE <b>SUPERVISOR DISTRICT</b>	DATE <b>MAY 4 1970</b>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAY 4 1970

GEORGE WASHINGTON UNIVERSITY  
LIBRARY