

UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY HOBBES, NEW MEXICO

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-069051

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

New Mexico "A" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Gladiola-Devonian

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 6, T12S, R38E

12. COUNTY OR PARISH 13. STATE

Lea

NM

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

ENSTAR Petroleum, Inc.

3. ADDRESS OF OPERATOR

P. O. Drawer 3546, Midland, TX 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)

At surface

660' FSL & 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3888' DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐  
☐

PULL OR ALTER CASING

☒  
☐  
☒  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

5-1/2" csg set @ 12,004'. Wolfcamp perms 9098' - 9700' open. Plan to set CIBP @ 9000' and dump 35' cmt on top. Cut off 5-1/2" csg @ approx 7850' and recover same. GIH w/tbg and circ hole w/9 ppg mud laden fluid. Spot 35 sx cmt plug ~~150'~~ 150' cut off csg stub. WOC 4 hrs and tag plug w/tbg. If in place - continue, if not - respot same. Set 35 sx plug from 5400' - 5500'. Set 35 sx plug 4455' - 4555' (btm of intermediate csg @ 4505')\* Set 35 sx plug 2943' - 3043' and 35 sx plug 2223' - 2323'. Set 15 sx plug at surface. Weld on plate and erect Dry Hole marker.

Plan to commence operations 7/5/83. MMS will be notified 24 hrs. prior to starting.

\* tag plug



18. I hereby certify that the foregoing is true and correct

SIGNED Sally M. Smith

TITLE Operations Manager

DATE June 22, 1982

(This space for Federal or State office use)

APPROVED

APPROVED BY PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUN 29 1983

\*See Instructions on Reverse Side