NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES OFFICE OCC

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, of the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

onal instructions in the Rules and R	Regulations of the Commission. Indicate Nature of Notice by (Thecking Below		
otice of Intention	Notice of Intention to Temporarily Abandon Well	N T	lotice of Intention o Drill Deeper	
OTICE OF INTENTION	Notice of Intention to Pluc Back	x	Notice of Intention to Set Lines	
PLUG WELL OTIGE OF INTENTION	Notice of Intention To Acidize	1	Notice of Intention to Shoot (Nitro)	
SQUEEZE OTICE OF INTENTION	Notice of Intention		Notice of Intention (Other)	
GUN PERFORATE	SION Hobbs, New Mexico	•	April 16, 196	2
IL CONSERVATION COMMISS ANTA FE, NEW MEXICO	SION Hobbs, Hew Mexico		(Date)	•••
entlemen:	tion to do certain work as described below	Su Su	nrey Mid-Continent	·····
Following is a Notice of Intent 011 Company	tion to do certain work as described below M. Powell or Operator) 128 , T		Vell Noin	(Unit)
(Company	or Operator) 128 35	NVDV	Gladiola	Pool
Nove in derrick pull	FULL DETAILS OF PROPOS FOLLOW INSTRUCTIONS IN THE I ing unit. Install BOP. Pull Of retainer on Lane Wells	l tubing an wireline 8	d Reda pump. 11,935'. Run 2 3/8"	tbg and loa
Move in derrick pull Set Baker Model "K" hole with cil. Set Pull the and WOC 24 Test casing and squa Perf & 11,978'. Run swab dry lead the wi breakdown. If negligible fluid	FULL DETAILS OF PROPOS FOLLOW INSTRUCTIONS IN THE I ing unit. Install BOP. Pull OI retainer on Lane Wells in Model "K" packer and eq hrs. Run bit and Rotevert sees job to 2000#. 2 3/6" the w/FB packer to ith oil and attempt to brea gal mad acid before next at is obtained may be necessar	tubing an wireline & meese perfs soraper. Dr approximate akdown forms tempt. Revenue to repend FB pack	d Reda pump. 11,935'. Run 2 3/8" 11,975-93'. 111 out cement to 1 11,940'. Swab to 12 11,940'. Swab to 13 11,940'. I arse out any acid re 14 12 13 14 15 15 15 15 15 15 15 15 15 15 15 15 15	test. If f will not maining after previous de
Move in derrick pull Set Baker Model "K" hole with cil. Set Pull the and WOC 24 Test casing and squa Perf & 11,978. Run swab dry lead the wi breakdown. If negligible fluid	FULL DETAILS OF PROPOS FOLLOW INSTRUCTIONS IN THE I ing unit. Install BOP. Pull OI retainer on Lane Wells in Model "K" packer and sq hrs. Run bit and Rotevert see job to 2000. 2 3/8" the w/FB packer to ith oil and attempt to breagal and acid before next at its obtained may be necessary duction obtained pull the install the install the see that it is obtained may be necessary duction with no oil show obtained with no oil show of the contract with no oil show obtained with no oil show of the contract with no oil show	tubing an wireline & wireline & weese perfs scraper. Dr approximate kdown forms tempt. Revenue to repend FB packs tained on s	d Reda pump. 11,935'. Run 2 3/8" 11,975-93'. 111 out cement to I all out cement to I all out cement to I are out any acid represent and acidise. For the Reda pump to Run Re	test. If f will not maining after previous d and abandom
Move in derrick pull Set Baker Model "K" hole with cil. Set Pull the and WCC 2k Test casing and squa Perf & 11,978'. Run swab dry load the wi breakdown spet 250 s breakdown. If negligible fluid If satisfactory pro- setting. If large water produ	FULL DETAILS OF PROPOS FOLLOW INSTRUCTIONS IN THE I ing unit. Install BOP. Pull OI retainer on Lane Wells in Model "K" packer and sq hrs. Run bit and Rotsvert bese job to 2000%. 2 3/8" the W/FB packer to ith oil and attempt to brea gal mud soid before next at is obtained may be necessed duction obtained pull the hotion with no oil show eb	tubing an wireline & meese perfs scraper. Dr spproximate addwn forms tempt. Revenue to repend on Sunray MIRA	d Reda pump. 11,935'. Run 2 3/8" 11,975-93'. 111 out cement to I by 11,940'. Swab to ition up to 4000#. I bree out any acid referate and acidise. For Run Reda pump to wab tests will plug continent oil company or operator standards.	test. If f will not maining after previous de and abandon
Move in derrick pull Set Baker Model "K" hole with sil. Set Pull the and WOC 24 Test casing and squa Perf @ 11,978'. Run swab dry lead the wi breakdown. If negligible fluid If satisfactory pro- setting. If large water produ	FULL DETAILS OF PROPOS FOLLOW INSTRUCTIONS IN THE I ing unit. Install BOP. Pull OI retainer on Lane Wells in Model "K" packer and sq hrs. Run bit and Rotsvert bese job to 2000%. 2 3/8" the w/FB packer to ith oil and attempt to brea gal mud soid before next at is obtained may be necessed duction obtained pull the hotion with no oil show eb	tubing an wireline & meese perfs scraper. Dr approximate actompt. Revenue to repeat the packet tained on stained on stain	d Reda pump. 11,935'. Run 2 3/8" 11,975-93'. 111 out coment to I by 11,980'. Swab to taken up to 1000%. I bree out any acid reference and acidize. For Run Reda pump to wab tests will plug for pany or Operator	test. If f will not maining after previous d and abandom