

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Petrus Oil Company, L. P.	8. Farm or Lease Name Houston "A"
3. Address of Operator 12377 Merit Drive, Suite 1600 Dallas, TX 75251	9. Well No. 1
4. Location of Well UNIT LETTER L 2310 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 19 TOWNSHIP 12 RANGE 38 NMPM.	10. Field and Pool, or Wildcat Gladiola-Devonian
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to perform the following work.

- Spot 50 sx plug at 9300-9600' to cover Wolfcamp perforations from 9398-9542'.
- Circulate the well full of 10 ppg mud mixed with 25# gel/bbl.
- Freepoint and cut 7" casing at ±8000'. POOH with casing.
- Spot 100' plug with 25 sx inside and 25 sx above top of 7" casing stub at approx. 8000'.
- Spot a 25 sx plug across the 9-5/8" casing shoe.
- Spot a 25 sx plug from 2200-2250' at the top of the salt.
- Spot a 10 sx surface plug and 4" OD steel marker that extends 4' above ground level.
The well name and number and location will be welded on the metal marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Suzanne Jourdan TITLE Regulatory Coordinator DATE 08-10-87

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE AUG 20 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 20 1987

OCD

HOBBS OFFICE