

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>DEPLETED</u>	7. Unit Agreement Name
2. Name of Operator PAN AMERICAN PETROLEUM CORPORATION	8. Farm or Lease Name <u>HOUSTON "A"</u>
3. Address of Operator BOX 68, HOBBS, N. M. 88240	9. Well No. <u>2</u>
4. Location of Well UNIT LETTER <u>L</u> , <u>2110</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>330</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>19</u> TOWNSHIP <u>12-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat <u>GLADIOLA WOLF CAMP</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3875' GL</u>	12. County <u>LEA</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well plugged and abandoned as follows:

1. Spotted 15 sz Cement plug 9550-9460 (Cover perfs 9536-9470) (CORRECT)
2. Shot 5 1/2" Casing 7470, 6500, 5500, + Pulled from 5020. Spotted 25 sz in and out of 5 1/2" stub.
3. 20 sz plug in + out of 9 7/8" Set at 4500'.
4. Shot 9 7/8" c 1500 + pulled from 1220. Spot 25 sz in + out of 9 7/8" stub @ 1220.
5. Spot 25 sz. in + out of 13 3/8 CSA 316'.
6. Spot 10 sz @ surface and erect P + A marker. 12-1-67

Subsequent report to be submitted upon final cleanup and ground restoration.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE AREA SUPERINTENDENT DATE 1-26-68

APPROVED BY John W. Runyan TITLE _____ DATE _____
1- NSW
CONDITIONS OF APPROVAL, IF ANY:
1- WFS Spencer-Tulsa
1- SUSP