

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER TA'd		5. LEASE DESIGNATION AND SERIAL NO. LC-064605	
2. NAME OF OPERATOR Amerada Hess Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Drawer D, Monument, New Mexico 88265		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1983' FNL & 548.46' FEL Unit H		8. FARM OR LEASE NAME Federal "B"	
14. PERMIT NO.		9. WELL NO. 2	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3810' DF		10. FIELD AND POOL, OR WILDCAT Bronco Siluro Devonian	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA Sec. 11, T13S, R38E	
		12. COUNTY OR PARISH Lea	13. STATE N.M.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plan to MIRU pulling unit & plugging unit. Remove well head & install BOP. TIH w/5.5 guage ring & junk basket to 11,752' & TOH. TIH w/5.5" CIBP & set at 11,752'. Circ. hole w/380 bbls. MLF & set 39 sks. on top of CIBP. Weld on 7" pull nipple Determine freepoint from stretch & jet cut 7" csg. at freepoint. TOH w/7" csg. TIH w/tbg. to 6850' & spot 80 sks. cement fr. 6850' - 6682' & TOH. TIH & perf. csg. at 2550'. TIH w/pkr. set at 2350' & displace cement 100' below pkr. w/1000 sks. cement. Release pkr. & TOH. Spot 5 sks. of cement at surface. Remove BOP & RDPU & plugging unit. Cut off well head 3' below surface & install dry hole marker. Cut off dead man anchors & clean location.

RECEIVED
MAY 4 8 41 AM '92
OFFICE OF THE
ATTORNEY GENERAL

18. I hereby certify that the foregoing is true and correct

SIGNED R. L. Whelan TITLE Supv. Adm. Svc.

DATE 4-29-92

(This space for Federal or State office use)

APPROVED BY David A. Glass TITLE _____

DATE 5-6-92

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side