

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
3-NMOCC
1-File

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-2576	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- NIO		7. Unit Agreement Name
2. Name of Operator GETTY OIL COMPANY		8. Farm or Lease Name STATE "BF"
3. Address of Operator P.O. BOX 249, HCBES, NEW MEXICO 88240		9. Well No. 2
4. Location of Well UNIT LETTER H, 1980 FEET FROM THE NORTH LINE AND 660 FEET FROM THE EAST LINE, SECTION 20, TOWNSHIP 12-S, RANGE 34-E, NMPM.		10. Field and Pool, or Wildcat RANGER LAKE-BOUGH C
15. Elevation (Show whether DF, RT, GR, etc.) 4164 D.F.		12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Run CIBP to 9850' and dumped 4 sxs. of cement on plug. 10-29-73.

Shut pipe @ 4200'. Pulled and layed down 5-1/2" casing. 11-2-73.

Mixed mud and circulated to surface. Ran tubing to 4219' and pumped 45 sxs. plug from 4219 to 4119'. 11-5-73.

Shot 8-5/8" @ 914' and pulled and layed down 8-5/8" casing. 11-6-73.

Run tubing to 964' and pumped a 40 sx. plug from 964 to 864'. 11-8-73.

Pulled tubing to 410' and spotted 60 sx. plug from 410 to 310'. 11-8-73.

Placed 10 sx. surface plug and placed "DRY HOLE MARKER". 12-6-73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY:

SIGNED C.L. WADE: C. L. Wade TITLE AREA SUPERINTENDENT DATE JANUARY 10, 1974

APPROVED BY: John W. Runyan TITLE: DATE:

CONDITIONS OF APPROVAL, IF ANY: