. COPIES RECEIV	ED					Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103				
SANTA FE		NEW MEXI	CO OIL CON	SERVATION COM	MISSION	Effective 1-1-65
FILE						5a. Indicate Type of Lease
U.S.G.S.						State X Fee
LAND OFFICE						5. State Oil & Gas Lease No.
OPERATOR						B-8638
						Virinininini
(DO NOT USE TH	SUN	DRY NOTICES AND R PROPOSALS TO DRILL OR TO D EATION FOR PERMIT - " (FORM	EPORTS ON	WELLS BACK TO A DIFFERENT EH PROPOSALS.)	T RESERVOIA.	
I. OIL X	GAS WELL	other- Temp	orarily	Abandone	1	7. Unit Agreement Name
2. Name of Operator Beren Corporation						8. Farm or Lease Name Levick State
3. Address of Operator						9. Well No.
1776 Linco	oln Str	eet, Suite 60]	. Denve	r. Colorad	do 80203	1
4. Location of Well		· · · · · · · · · · · · · · · · · · ·				10. Field and Pool, or Wildcat
UNIT LETTER	<u> </u>	1980 FEET FROM TH	Sout	h_LINE AND	660 FEET FROM	Tobac Penn
THE East	LINE, SE	20 Town	м _{энтр} 85	RANGE	33E NMPM.	
mmm	mn	15. Elevation	(Show whether	DF, RT, GR, etc.)	12. County
			4391'			Chaves
16.		k Appropriate Box T				
N	OTICE OF	INTENTION TO:			SUBSEQUENT	REPORT OF:
,	[F]	PING AN	D ABANDON	REMEDIAL WORK		ALTERING CASING
PERFORM REMEDIAL WOR	** <u>K.</u>	, FE00 AM	b Abanbon <u>F</u>	COMMENCE DRILL	ING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING	H	Change	PLANS	CASING TEST AND	F	
POLE OR ALTER CASING			•	OTHER		
OTHER						
				<u> </u>		estimated data of starting for proposal
17. Describe Proposed work) SEE RULE	or Completed	Operations (Clearly state	all pertin ent d e	tails, and give pert	inent dates, including	estimated date of starting any proposed
recovering squeezed, However, ifollowing	stuck the ho f unsu manner	sed that collated tubing. If some cleaned out coessful, we provided the contract of the contra	ccessfu , and to lan to	 the mile he well re plug and a 	lled area w eturned to abandon the	production. well in the
C	cement	ing to collaps and displace t en brine.	se in 4½ so perfo	" casing (rations @	05750', spo 8996'-9005'	t 100 sx with
	Run and 15750'. olug.	set abandonme Load hole wit	ent plug ch mud l	in 4½" ca aden brine	asing above e and spot	collapse 100' cement
		$4lac{1}{2}$ " casing at of cut off cas		oint and s	spot 100' c	ement plug
		-CONTI	NUED ON	PAGE TWO-	•	
18. I hereby certify tha	t the informa	tion above is true and comp	lete to the best	of my knowledge a	nd belief.	
(1)/	/ M	This is	~		Engineer	DATE 03/13/75
SIGNED_	og //	1111	TITLE			
		Orig. Stage 3 b				DATE
APPROVED BY		Joe D. Former Dist. F. Shore	TITLE	·		
CONDITIONS OF APP	ROVAL, IF	luys Thra	tuk	nrg		

-Page Two-

17. (Continued):

- (4) Pull casing to 3645' and spot 100' cement plug at 7 5/8" casing shoe. Pull and lay down $4\frac{1}{2}$ " casing.
- (5) Move out service unit and move in casing recovery unit when available.
- (6) Remove casing head. Latch onto 7 5/8" casing, cut off at free point and pull.
- (7) Run tubing to top 7 5/8" stub and spot 100' cement plug. Pull tubing to 386' and spot 100' cement plug at 10 3/4" casing shoe.
- (8) Cut off casing head and cap with 10 sx cement and install dry hole marker.
- (9) Cut dead men and clean location.