

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LH-985	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER- <input type="checkbox"/>
Name of Operator Harvey E. Yates Company		
Address of Operator P. O. Box 1933, Roswell, New Mexico 88201		
Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>12S</u> RANGE <u>36E</u> NMPM.		

7. Unit Agreement Name
8. Farm or Lease Name Cameron State
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Lea

11. Elevation (Show whether DF, RT, GR, etc.) 4009'
--

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	
ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

3/30/84 GIH w/tbg open ended to 12,244'. Spot 45 sx cmt plug. Pull 15 stands & rev out.
3/31/84 GIH w/tbg, tag cmt @ 12,144'. Spot the following 35 sx 100' plug:

9865' to 9765'
9413' to 9313'
8013' to 7913'
7265' to 7165'
5935' to 5835'
4500' to 4400'

Pull 15 stands.

4/01/84 GIHw/tbg & tag cmt @ 4400'. Spot 35 sx 100' plug from 1600' to 1500' & 400' to 300'.
set a salt plug @ 1600'. Put 10 sx plug @ surface. Install dry hole marker.
RD & release unit. Well P & A 1:PM 3/31/84.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED a. J. Deans TITLE V. P. of Operations DATE April 3, 1984

APPROVED BY JERRY SEXTON DISTRICT 1 SUPERVISOR TITLE DATE APR 10 1984

CONDITIONS OF APPROVAL, IF ANY:

APR 10 1984
C.C.D.
HOBBS OFFICE