

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State ☐	Fee ☒
3. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name Bettenbough Unit	
Name of Operator Harvey E. Yates Company		8. Farm or Lease Name	
Address of Operator P.O. Box 1933, Roswell, New Mexico 88201		9. Well No. 1	
Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM West LINE, SECTION 32 TOWNSHIP 13S RANGE 36E N.M.P.M.		10. Field and Pool, or Wildcat Und. Bough	
15. Elevation (Show whether DF, RT, GR, etc.) 3975 GL		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PLUG OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☒ CHANGE PLANS ☐ OTHER ☐	REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐ OTHER ☐
---	---	--	---

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Casing and Cement Program:

17 1/2" hole 13 3/8 csg. 48#, set @ 369 400 SKS, est top @ surface
 12 1/4" hole 9 5/8 csg. 40#, set @ 4600 3400 SKS, est top @ surface
 7 7/8" hole 5 1/2 csg. 20 & 17#, set @ 13,150, est top @ 8460 (CBL)

Recommended Procedure

- Pump cement plugs as follows:
250' plug from 10,350' to 10,100' (across perfs and tag)
100' plug from 9900' to 9800' (top of Wolfcamp)
- Run free point of 5 1/2" csg.
- Cut and pull approximately 8000' plus or minus of 5 1/2" csg.
- Pump cement plugs as follows:
100' plug @ 5 1/2" cut off (50' in and out) and tag.
100' plug from 4650' to 4550' (across interm. shoe).
100' plug from 3050' to 2950' (base of Salt).
100' plug from 2200' to 2100' (top of Salt).
50' plug @ surface

5. Install dry hole marker. NOTE: VERBAL APPROVAL OBTAINED FROM EDDY SEAY ON 5-20-86

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Jerry Sexton TITLE Production Manager DATE March 26, 1987

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISRICT SUPERVISOR TITLE DISRICT SUPERVISOR DATE MAR 30 1987

ADDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAR 30 1987
OCD
HOBBS OFFICE