

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

Oct 14 10 32 AM '65

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
K-3359

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name --
2. Name of Operator <del>TRAINER CORPORATION</del> C. W. TRAINER	8. Farm or Lease Name King
3. Address P. O. Box 1100 Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER P, 660 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 2 TOWNSHIP 14-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat King Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3836 GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☒  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug and abandon this well as follows:

1. Spot 25 sx plug 12,300'-12,688'.
2. Cut off 4 1/2" casing at freepoint - 11,000' I hope - and pull.
3. Spot 25 sx. plug in and out of 4 1/2" casing stub.
4. 25 sx. plug @ 10,100'.
5. 25 sx. plug @ 9,200'.
6. 25 sx. plug @ 7,300'.
7. 25 sx. plug @ 5,600'.
8. Spot 25 sx. plug 4,625' - 4,700'.
9. Cut off 9 5/8" casing at freepoint and pull.
10. Spot 25 sx. plug in and out of 9 5/8" casing stub.
11. 25 sx. plug @ 2,200'.
12. Spot 25 sx. plug 275' - 325'.
13. Set regulation marker in 10 sx. at surface.
14. Level and clean location for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED By: C. W. Trainer TITLE President DATE October 13, 1965  
APPROVED BY: Joe L. Gomez TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

