

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-1027

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name New Mexico 'CZ' State
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 2
4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 14 TOWNSHIP 12-S RANGE 34-E N.M.P.M.	10. Field and Pool, or Wildcat Ranger Lake Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4152' (DF)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well has been plugged and abandoned as listed below:

1. Circulate hole with mud.
2. Spotted 40 sx cement plug from 9875' - 10300'.
3. Cut 4-1/2" OD casing at 4150' and pull.
4. Spotted 25 sx cement plug from 4100' - 4200'.
5. Spotted 10 sx cement plug at surface.
6. Set 4" marker extending 4' above ground level and clean location.
Plug and abandon complete February 26, 1970.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *John W. Runyan* TITLE **Assistant District Superintendent** DATE **February 27, 1970**

APPROVED BY *John W. Runyan* TITLE **Geologist** DATE **3/1**

CONDITIONS OF APPROVAL, IF ANY: