

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANCTUARY	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-10076	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator TEXACO Inc.		8. Farm or Lease Name M. M. "EV" St. HCT-2
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240		9. Well No. 3
4. Location of Well UNIT LETTER M 990 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 13-S RANGE 33-E NMPM.		10. Field and Pool, or Wildcat Lazy J Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4205' (DF)		12. County lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Addl perfs in Penn Zone <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- RIG UP. PULL RODS AND PUMP. INSTALL BOP. PULL TUBING.
- PERFORATE 4 1/2 " CASING W/2-JSPF @ 9698', 99', 9717', 9719', 9855', 77', 88', 93', AND 9895'.
- SET RBP @ 9920' AND PACKER @ 9765'. ACIDIZE PERFS 9805' TO 9895' W/2000 GALS 20% NEFE ACID IN 2-EQUAL STAGES USING 16 BALL SEALERS.
- RESET RBP @ 9765' AND PACKER @ 9650'. ACIDIZE PERFS 9698' TO 9751' W/2000 GALS 20% NEFE ACID IN 2-EQUAL STAGES USING 16 BALL SEALERS. FLUSH WELL.
- INSTALL PUMPING EQUIPMENT. TEST AND PLACE ON PRODUCTION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie Seay TITLE Asst. Dist. Mgr. DATE 7-6-83

ORIGINAL SIGNED BY EDDIE SEAY  
OIL & GAS INSPECTOR

JUL 8 1983

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: