

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-9380

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name N. M. 'AQ' St. NCT-11
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM East 3 LINE, SECTION 14-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Lazy J Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4225' (DF)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Addl Perfs In The Same Zone <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- RIG UP. PULL RODS AND PUMP. INSTALL BOP. PULL TUBING.
- PERFORATE 4 1/2" CASING W/2-JSPF @ 9427', 38', 41', 43', 9546', 51', 54', 9731', 33', 35', 42', 52', & 9761'.
- SET RBP @ 9950' AND PKR @ 9810'. ACIDIZE PERFS 9849'-9931' W/2000 GAL 15% NEFE HCL ACID AND 20 BALL SEALERS.
- RESET RBP @ 9810' AND PKR @ 9650'. ACIDIZE PERFS 9731' - 9761' W/1500 GALS 15% NEFE ACID & 20 BALL SEALERS.
- RESET RBP @ 9650' AND PKR @ 9350'. ACIDIZE PERFS 9427' - 9554' W/2000 GALS 15% NEFE HCL ACID & 20 BALL SEALERS.
- PULL PKR AND RBP. INSTALL PUMPING EQUIPMENT. TEST AND RETURN TO PRODUCTION.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst Dist Mgr DATE 6-20-84

APPROVED BY JERRY SEXTON DISTRICT SUPERVISOR TITLE DATE JUN 22 1984

CONDITIONS OF APPROVAL, IF ANY: