

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

OG-5343

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name State "FO"
3. Address of Operator P.O. BOX 68, HOBBS, NEW MEXICO 88240	9. Well No. 3
4. Location of Well UNIT LETTER <u>F</u> <u>2080</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>13-S</u> RANGE <u>34-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Nonombre Upper Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4157.6' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐PLUG AND ABANDON ☒
CHANGE PLANS ☐OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to P&A the subject well as follows, MISW and POH w/ tbg and pkr. RIH w/ CRBP and SA 10,200'. Cap w/ 35' of cmt. (Class H neat). Pull up and spot above cmt, 52 bbl of 10# brine w/ 25 # gel / bbl and POH. RIH and perf 8000'-01' w/ 45PF. RIH w/ cmt ret and tbg. Set ret at 7850' and pump 50 sx class H neat cmt. Squeeze perms 8000'-01'. (Top of Abo ~7937'). Sting out of cmt ret and dump excess cmt. Pull up and spot above cmt and ret, 50 bbl 10# brine w/ 25 # gel / bbl. and POH. RIH and perf 5800'-01' w/ 45PF. RIH w/ cmt ret and SA 5680'. Pump 50 sx class H neat cmt and sgz perms 5800'-01'. (Top of Glorieta ~5743') Sting out of cmt ret and dump

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE

ADMINISTRATIVE ANALYST

DATE

16 August 1985

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT SUPERVISOR

TITLE

DATE

AUG 20 1985

excess cmt. Pull up and spot above cmt and ret, 32 bbl 10# brine w/ 25# gel / bbl. and POH. RIH and perf 4325'-26' w/ 4SPF. RIH w/ cmt ret and SA 4225'. Pump 60 sx class H neat cmt. Squeeze perfs 4325'-26' ($8\frac{5}{8}$ " csg shoe ~ 4275'). Sting out of cmt ret and dump excess cmt. Pull up and spot above cmt and ret 40 bbl of 10# brine w/ 25# gel / bbl. and POH. RIH and perf 2550'-51' w/ 4SPF. RIH w/ cmt ret and 2450' and pump 50 sx class H neat cmt. Squeeze perfs 2550'-01' (Top cmt $8\frac{5}{8}$ " csg ~ 2500'). Sting out of ret and dump excess cmt. Pull up and spot above cmt and ret 50 bbls of 10# brine w/ 25# gel / bbl and POH. RIH and perf 375'-76' w/ 4SPF. RIH w/ pkr and tag. Set pkr at 150' and establish circ w/ both the $8\frac{5}{8}$ "- $13\frac{3}{8}$ " and $5\frac{1}{2}$ "- $8\frac{5}{8}$ " annuli. Flush cmt 125' below pkr w/ 3.5 bbl. brine. Rel pkr and spot above cmt plug 4 bbl of 10# brine w/ 25# gel / bbl. and POH. RIH and spot a 10 sx class H neat cmt plug from 100' to surface. Cap well and erect abandonment marker. MOSU.

RECEIVED
AUG 19 1985
HODGE OFFICE