			- Form C-103
JF COPIES RECEIVED			4 Supersedes Old
DISTRIBUTION			C-102 and C-103
ITA FE	NEW MEXICO DIL CON	SERVATION COMMISSION	Effective 1-1-65
LE			
J.S.G.S.			5a. Instrate Type of Lease
AND OFFICE			State X Fee
PERATOR			5. State Cil & Gas Lease No.
			E-906
(DO NOT USE THIS FOUN FON	DRY NOTICES AND REPORTS ON PROPUSALS TO DRILL OF TO DEEPEN OF PLUG	BACK TO A DIFFERENT RESERVOIR.	
	OTHER.		7. Unit Agreement Name
, Mane of Crentor		8. Farm of Lease Name	
Phillips Petroleum Company			Ranger
Address of Cretator			9. Well No.
Room 401, 4001 Penbro	ook Street, Odessa, Texas	/9/62	15
. Location of Well			10. Field and Pool, or Wildcat
C	1980 FEET FROM THE West	660 -	Ranger Lake - Bough
UNIT LETTER	FEET FROM THECOL	CINE AND P	
		0/ =	
THE North LINE, SE	CTION 26 TOWNSHIP 12-S	RANGE34-E	-*MPM. X////////////////////////////////////
			12. County
///////////////////////////////////////	15. Elevation (Show whethe		
	4146' G	R	Lea
	ck Appropriate Box To Indicate		
NOTICE OF	F INTENTION TO:	SUBSE	EQUENT REPORT OF:
	5		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLIG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER	
		<u></u> וו	
OTHER			
2. Describe Erchosed or Complete	d Operations (Clearly state all pertinent de	tails, and give pertinent dates,	including estimated date of starting any proposed
worki see rule 1103.			
. Install BOP, pull	tubing and hydraulic equi	pment.	
. Run in hole w/200'	of tail pipe and 2-3/8"	tbg to 9980'. Tail	pipe to be run through Baker
Model 415-D pkr at	- + 9786'		
Spot 50 ave of Cla	as H cmt from 9980' to 95	50'. Pull tbg to 9	300' and reverse clean.
	les must be above permanen	t nkr at 9786'. Lo	ad hole w/9.5#/gal mud laden
. Tag top of cmt. 1	Op must be above permanen		
fluid. Come out o	of hole with tubing.	1 7000	
• Pull and cut 5-1/2	2" casing. TOC approximat	ely /200°.	When the 70001 Displace
. Run in hole w/tbg	to 50' below csg cutoff.	Spot 65 sxs of Cla	ss H cmt to 7000'. Displace
cmt w/9 5 #/gal much	l laden fluid.		
. Raise tbg to 4300	'. Spot 65 sxs of Class H	cmt to 4100'. Dis	place cmt w/mud laden fluid.
$\begin{array}{c} \text{Raise bb to 4000} \\ \text{Paige the to 3000} \end{array}$. Reverse clean and come	out of hole.	
	8" casing. TOC approximat	elv 3150'	
• Full and cut $\delta = 5/\delta$	101 + 1 = 0 = 100 = 1 = 0 = 100	Il and autoff Shot	100 sxs of Class H cmt to
	/8" tbg to 50' below 8-5/8		100 0A0 01 01000 A 010 00
. Run in hole $w/2-3$,		aen 11ula.	and the second ladon fluid
approvimately 3000	0'. Displace cmt w/mud la		ace cmr w/ming laden i tuto.
approximately 3000 0. Raise the to 363'	. Spot 75 sxs of Class H	cmt to 263°. Dispi	ace che wymee heers
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100'	. Spot 75 sxs of Class H . Spot 75 sxs of Class H	cmt to surface.	
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100'	. Spot 75 sxs of Class H . Spot 75 sxs of Class H	cmt to surface.	
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100'	. Spot 75 sxs of Class H . Spot 75 sxs of Class H weld on plate, install pe	cmt to surface. ermanent marker, and	fill in hole.
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100'	. Spot 75 sxs of Class H . Spot 75 sxs of Class H weld on plate, install pe THE COM	cmt to surface. ermanent marker, and MISSION AUGT B5 NOTH	l fill in hole. FED 24
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100' 2. Cut off wellhead,	. Spot 75 sxs of Class H . Spot 75 sxs of Class H weld on plate, install pe iHE COM HOLDS PE	cmt to surface. ermanent marker, and MISSION AUGT BE NOTH	fill in hole.
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100' 2. Cut off wellhead,	. Spot 75 sxs of Class H . Spot 75 sxs of Class H weld on plate, install pe iHE COM HOLDS PE	cmt to surface. ermanent marker, and MISSION AUGT BE NOTH	fill in hole.
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100' 2. Cut off wellhead,	. Spot 75 sxs of Class H . Spot 75 sxs of Class H weld on plate, install pe THE COM	cmt to surface. ermanent marker, and MISSION AUGT BE NOTH	fill in hole.
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100' 2. Cut off wellhead,	. Spot 75 sxs of Class H . Spot 75 sxs of Class H weld on plate, install pe	cmt to surface. ermanent marker, and MISSION AUGT BE NOTH WOR TO THE BECINGIN CORRATIONS FOR THE MOVED	I fill in hole. FIED 24 IG OF <u>C-103</u>
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100' 2. Cut off wellhead,	. Spot 75 sxs of Class H . Spot 75 sxs of Class H weld on plate, install pe	cmt to surface. ermanent marker, and MISSION AUGT BE NOTH WOR TO THE BECINGIN CORRATIONS FOR THE MOVED	I fill in hole. FIED 24 IG OF <u>C-103</u>
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100' 2. Cut off wellhead,	. Spot 75 sxs of Class H . Spot 75 sxs of Class H weld on plate, install pe	cmt to surface. ermanent marker, and MISSION AUGT BE NOTH WOR TO THE BECINGIN CORRATIONS FOR THE MOVED	I fill in hole. FIED 24 IG OF <u>C-103</u>
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100' 2. Cut off wellhead,	. Spot 75 sxs of Class H . Spot 75 sxs of Class H weld on plate, install pe 	cmt to surface. ermanent marker, and MISSION AUGT BE NOTH WOR TO THE BECINGIN CORRATIONS FOR THE MOVED	I fill in hole. FIED 24 IG OF C-103 Pecialist CATE October 23, 1979
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100' 2. Cut off wellhead,	 Spot 75 sxs of Class H Spot 75 sxs of Class H weld on plate, install period THE COM HOULS PI HOULS PI PILCIPAC A state of the provided sta	cmt to surface. ermanent marker, and MISSION AUGT BE NOTH WOR TO THE BECINGIN CORRATIONS FOR THE MOVED	I fill in hole. FIED 24 IG OF C-103 Pecialist mare October 23, 1979
approximately 3000 0. Raise tbg to 363' 1. Raise tbg to 100' 2. Cut off wellhead,	. Spot 75 sxs of Class H . Spot 75 sxs of Class H weld on plate, install pe	cmt to surface. ermanent marker, and MISSION AUGT BE NOTH WOR TO THE BECINGIN CORRATIONS FOR THE MOVED	I fill in hole. FIED 24 IG OF <u>C-103</u>