


MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210

TELEPHONE (505) 748-1471

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

OK JS sent in well 7.6

November 18, 1994

New Mexico Oil Conservation Division
P. O. Box 1980
Hobbs, New Mexico 88240

ATTN: Jerry Sexton

Dear Mr. Sexton:

As we discussed on the phone yesterday, we are writing this letter concerning the Abo perforations in the Childress AKV #2 in L 1-14S-33E, 1980' FSL & 660' FWL (previously "Childress A #1").

The Abo perforations (8836-8914) in this well were left open by the previous operator when they plugged the well. We re-entered the well in August, 1994. We had a slight show in the Abo as we drilled out the plugs to TD. We did not squeeze the Abo perms. We completed the well in the Bough zones.

We are requesting permission to do nothing to the Abo perforations until the well is ready to plug. Please call should you need further information.

Sincerely,

Theresa Sloan
Petroleum Engineer