

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K 6207	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/> Dry	7. Unit Agreement Name
2. Name of Operator Delaware-Apache Corporation	8. Farm or Lease Name State 30
3. Address of Operator 1720 Wilco Building Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER H 660 FEET FROM THE East LINE AND 1980 FEET FROM THE North LINE, SECTION 30 TOWNSHIP 13S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) Gr 4275	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-9-68 25 sx plugs set at 9890', 9650', 7545', 5222', 4091'

As per Mr. L. A. Clements, 11-20-70, propose to set the following plugs

Set 25 sx in and out of stub where 8-5/8" csg is shot off

If we expose the salt, set 25 sx at base and top.

Set 25 sx at stub of 11-3/4" csg - 352'.

10 sx set at surface with marker for dry hole.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bonnie Husband TITLE Production Clerk DATE 11-20-70

APPROVED BY [Signature] TITLE Director DATE

CONDITIONS OF APPROVAL, IF ANY: