NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

		L	*/\DBc	Supersedes Old
DISTRIBUTIO	N		OBBS	C-102 and C-103
SANTA FE		NEW MEXICO C	DIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		File	N 19 of Waga	5a. Indicate Type of Lease
U.S.G.S.				
LAND OFFICE				State X Fee 5. State Oil & Gas Lease No.
OPERATOR		۾ ل		B-10980
<del></del>				<del>- kummummu</del>
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)			<del></del>	
OIL X	GAS WELL	OTHER•		7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name			
Coogtol St	State"32" Com			
Coastal St 3. Address of Operat	9. Well No.			
P. O. Box	2			
P. O. Box 235, Midland, Texas 79701				10. Field and Pool, or Wildcat
UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM				Baum (Upper Penn)
	•			
West	LINE SEC	TION 32	13S RANGE 33E	имрм. (
, , , , , , , , , , , , , , , , , , ,	- CINEY SEC	1000		
mmm		15. Elevation (Sho	w whether DF, RT, GR, etc.)	12. County
		4272 GL		Lea
16.	Check	Appropriate Boy To In	dicate Nature of Notice, Repo	
		INTENTION TO:	<del>-</del>	SEQUENT REPORT OF:
	NOTICE OF	INTENTION TO.	, sob	SEQUENT REPORT OF:
PERFORM REMEDIAL	w.o.e.v. [	PLUG AND ABA	NDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABAND	=	, 200 Allo Aba	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CAS!	<del></del>	CHANGE PLANS	<b>┌</b> ──	<del></del>
PULL ON ALIEN CASI	"	anange react	OTHER	·
OTHER			01,828	
OTHER				
17. Describe Propos	ed or Completed	Operations (Clearly state all pe	rtinent details, and give pertinent dates	, including estimated date of starting any proposed
work) SEE RUL		1.5.1 12.2 (0.1	Alla Danna (Hanan Danna) I	Deal Wallering completion
				ool. Following completion,
				start plugging operations
on 5-20-69	9. The pro	ocedure for plugging	g well will be as follow	7S:
		. 1 11 00001	5 5 1 /011	•
1. i	Rig up. Ci	ut and pull 8000' of	r 5-1/2".	
2. (	Cut and pu	11 2300' of 8-5/8".		
	D1 / ^	1 1	0.1	
3. I	Place 40 sa	acks plug at 9850-60	0'.	// /
Place 25 sacks plug at 8000' (5-1/2" casing stub).  Place 50 sacks plug at 4080'.  Place 50 sacks plug at 2300' (8-5/8" casing stub).  Place 10 sacks plug at surface.				
1	Place 50 sa	acks plug at 4080'.		
]	Place 50 s	acks plug at 2300'	(8-5/8" casing stub).	action to The 14
	Place 10 s	acks plug at surface	e.	
				22 5x5 (1 1 / 4 - 1 1 -
4. 1	Weld steel	plate on top and in	nstall dry hole marker.	
			,	
		lan abana la torre and the state of the stat		
18, I nereby certify t	mat the informati	on above is true and complete to	the best of my knowledge and belief.	
	0/1-			
SIGNED_	Phon	WIX .	Division Production	Manager DATE May 16, 1969

[....