

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Mid-West Oil Corporation	8. Farm or Lease Name New Mexico
3. Address of Operator c/o Hobbs Pipe & Supply Company, Box 2010, Hobbs, N.M.	9. Well No. #1
4. Location of Well UNIT LETTER P ; 660 FEET FROM THE South LINE AND 510 FEET FROM THE East LINE, SECTION 5 TOWNSHIP 14 RANGE 34 NMPM.	10. Field and Pool, or Wildcat Ranger Lake
15. Elevation (Show whether DF, RT, GR, etc.) 4150' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot a 100' plug to cover all existing perforations.
2. Load hole with mud-laden fluids.
3. Pull approx. 5,500' of 5½" casing.
4. Spot a 100' plug in and out of casing stub.
5. Spot a 100' plug in and out of shoe of intermediate casing, approx. 4336'.
6. Spot a 100' plug at stub of 8-5/8" casing.
7. Spot a 100' plug in and out of the base of 11-3/4" surface casing, 318'.
8. Spot a 10 sx top hole plug and erect a regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Stanley Siskin by him</u>	TITLE <u>AGENT</u>	DATE <u>Jan. 8, 1973</u>
HOBBS PIPE AND SUPPLY COMPANY		
APPROVED BY <u>Joe D. Ramey</u>	TITLE <u>Dist. I. Supv.</u>	DATE <u>JAN 10 1973</u>
CONDITIONS OF APPROVAL, IF ANY:		