	 1		Form C-103
NO. OF COPIES RECEIVED	-	Supersedes Old	
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION			C-102 and C-103 Effective_1-1=65
SANTA FE	- NEW MEXICO DIE CONS	DEC	FIVFD
FILE	\dashv	\	5a. Indicate Type of Lease
U.S.G.S.	-		State Fee X
OPERATOR		MAR	2 San ON Os Gas Lease No.
			······································
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO ORILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (DO NOT USE THIS FORM FOR PROPOSALS TO ORILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (DO NOT USE THIS FORM FOR PROPOSALS.)			7. Unit Agreement Name
1. OIL GAS DRY HOLE WELL OTHER-			8. Farm or Lease Name
2. Name of Operator			DYE
JACK L. McClellan			9. Well No.
3. Address of Operator			
P. O. Box 848, Roswell, New Mexico 88201			10. Field and Pool, or Wildcar
4. Location of Well	660 FREY FROM THE SOUTH	660	1 NOESTATED
FAST	ction 28 township 13S	RANGE 34ENMPM.	
THE LAST LINE, SE	CTION TOWNSHIP	RANGE	
THINITINITY OF THE STATE OF THE	15. Elevation (Show whethe	r DF, RT, GR, etc.)	12. County
	4145' G.	L	LE A
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
	= INTENTION TO:	SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X		ALTERING CASING
TEMPORARILY ABANDON	_	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
	_	OTHER	
OTHER		J]	
17. Describe Proposed or Complete work) SEE RULE 1103.	ed Operations (Clearly state all pertinent de	etails, and give pertinent dates, including	estimated date of starting any proposed
·			
Proposs To Pills	S AND ABANDON THE ABOV	E TEST AS FOLLOWS:	
PROPOSE TO PLUG AND ABANDON THE ABOVE TEST AS FOLLOWS:			
WITH WELL FULL OF DRILLING MUD, SET 50 SACK CEMENT PLUG AT 9650' OR DEEPEST DEPTH POSSIBLE. PLACE 25 SACK PLUG IN AND OUT OF 42" CASING CUT			
DEEPEST DEPTH POSSIBLE. PLACE 25 SACK PLUG IN AND OUT OF 42" CASING CUT			
OFF. IF GLORIETA ZONE IS EXPOSED, WILL PLACE 25 SACK PLUG AT TOP OF			
DEEPEST DEPTH POSSIBLE. PLACE 25 SACK PLUG IN AND OUT OF 42 CASING COTOF. IF GLORIETA ZONE IS EXPOSED, WILL PLACE 25 SACK PLUG AT TOP OF SECTION. PLACE 25 SACKS IN AND OUT OF STUB OF 8-5/8" CASING, 25 SACK PLUG AT TOP OF SALT, 25 SACK AT BOTTOM OF 13-3/8" SURFACE CASING, 10 SACKS AT			
SURFACE, INSTALL DRY HOLE MARKER AND CLEAN LOCATION.			
SURFACE, INSTAL	L DRY HOLE MARKER AND	CLEAN LOCATION.	
	•		
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
18. I hereby certify that the inform	action above to true and complete to the box		
P M: F	20.00	OPERATOR	3-20-70
SIGNED IN.	1111		
	& Alan	to the second of	s and the specific of the second

CONDITIONS OF APPROVAL, IF ANY: