

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-23073</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <u>State "DM"</u> <u>Baum Upper Penn</u>
8. Well No. <u>DM #1-P</u>
9. Pool name or Wildcat <u>Baum Upper Penn</u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator <u>BRIDGE OIL COMPANY L.P.</u>
3. Address of Operator <u>12377 Merit Drive Suite 1600 Dallas, Tx 75251</u>	4. Well Location Unit Letter <u>P</u> : <u>460</u> Feet From The <u>5</u> Line and <u>660</u> Feet From The <u>E</u> Line Section <u>18</u> Township <u>13</u> Range <u>33E</u> NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. CIBP capped w/35ft. cmt or 100 ft. plug and tag
2. load hole w/10# salt gel
3. 100 sx plug top Abc 7500
4. cut and pull 5-1/2 casing 5000 \pm 100ft. plug 50in/50out and tag
5. 100 ft. plug at 8-5/8 shoe 50in/50out and tag
6. cut and pull 8-5/8 casing 1500 ft. \pm 100ft. plug 50in/50out and tag
7. 100ft. plug at 13-3/8 shoe 50in/50out and tag
8. 10 sx surface plug

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Olander Baxter TITLE _____ DATE 6-21-90
(915)
TYPE OR PRINT NAME OLANDER BAXTER TELEPHONE NO. 694-5464

(This space for State Use)

Eddie W. Seay
Oil & Gas Inspector

JUN 21 1990

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____