

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K 6607	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Coastal States Gas Producing Company		8. Farm or Lease Name State 1
3. Address of Operator P. O. Box 235, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER H , 1874 FEET FROM THE north LINE AND 554 FEET FROM THE east LINE, SECTION 1 TOWNSHIP 14-S RANGE 32-E NMPM.		10. Field and Pool, or Wildcat Baum (Upper Penn)
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP at 9480'.
2. Set 4 sx. plug 9445-9480' (dump bailer).
3. Cut 5-1/2" casing. Recovered 4500'.
4. Set 30 sx. plug at 4440-4540'.
5. Set 35 sx. plug at 3944-4044'.
6. Cut and recovered 1000' of 8-5/8" casing.
7. Set 40 sx. plug at 954-1054'.
8. Set 78 sx. plug at 270-372'.
9. Set 10 sx. plug at 0-15'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J.B. Shepherd TITLE Dist. Prod. Manager DATE 1-15-74

APPROVED BY Nathan E. Chigg TITLE OIL & GAS DATE

CONDITIONS OF APPROVAL, IF ANY: