ubmit 3 Copies o Appropriate	State of New Mexico Energy, Minerals and Natural Resources Departme	ent Form C-103 Revised 1-1-89	
District Office DISTRICT I 2.0. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISIO P.O. Box 2088 Santa Fe, New Mexico 87504-2088	WELL API NO. 30-025-23266	
O. Drawer DD, Anesia, NM 88210		5. Indicate Type of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No. OG-5217	
(DO NOT USE THIS FORM FOR PI DIFFERENT RES (FORM	TICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK T ERVOIR. USE "APPLICATION FOR PERMIT" C-101) FOR SUCH PROPOSALS.)	TO A 7. Lease Name or Unit Agreement Name New Mexico "R" State	
I. Type of Weil: OIL GAS WELL X WELL	OTHER		
2. Name of Operator		8. Well No. 2	
Headington Oil Compan 3. Address of Operator	ly	9. Pool name or Wildcat	
7557 Rambler Road, Su	iite 1100, Dallas, Texas 75231	Cerca Upper Penn	
4. Well Location Unit LetterH:21	29 Feet From The North Line and	Ter Out	
Section 33	Township 13S Range 34E 10. Elevation (Show whether DF, RKB, RT, GR, e		
	4140' GR		
II. Chec NOTICE OF I	k Appropriate Box to Indicate Nature of Not NTENTION TO:	SUBSEQUENT REPORT OF	
	PLUG AND ABANDON X REMEDIAL WO CHANGE PLANS COMMENCE D		
	PLUG AND ABANDON X REMEDIAL WO CHANGE PLANS COMMENCE D		
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WO CHANGE PLANS COMMENCE D CASING TEST OTHER:	AND CEMENT JOB	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed O work) SEE RULE 1103. Set CIBP @ 10,275' w Cut 5-1/2'' productio WOC and tag plug. P @ 2500' and pull cas Pump 70sx cement plu	PLUG AND ABANDON X REMEDIAL WO CHANGE PLANS COMMENCE D CASING TEST	PRILLING OPNS. PLUG AND ABANDONMENT AND CEMENT JOB ues, including estimated date of starting any proposed x cement plug from 7850'-8070'. Pump 25sx cement plug 6135'-6250'. O'. Cut 8-5/8'' intermediate casing 50'-2550'. WOC and tag plug.	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed O work) SEE RULE 1103. Set CIBP @ 10,275' w Cut 5-1/2'' productio WOC and tag plug. P @ 2500' and pull cas Pump 70sx cement plu	PLUG AND ABANDON X REMEDIAL WO CHANGE PLANS COMMENCE D CASING TEST OTHER: perations (Clearly state all pertinent details, and give pertinent data the 35' of cement on top. Pump 25s on casing @ 2500' and pull casing. Pump 30sx cement plug from 4250'-435 sing. Pump 50sx cement plug from 24 the from 400'-500'. Pump 10sx cement el and weld on steel cap.	PRILLING OPNS. PLUG AND ABANDONMENT AND CEMENT JOB ues, including estimated date of starting any proposed x cement plug from 7850'-8070'. Pump 25sx cement plug 6135'-6250'. O'. Cut 8-5/8'' intermediate casing 50'-2550'. WOC and tag plug.	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed O work) SEE RULE 1103. Set CIBP @ 10,275' w Cut 5-1/2" productio WOC and tag plug. P @ 2500' and pull cas Pump 70sx cement plu 3' below ground leve	PLUG AND ABANDON X REMEDIAL WO CHANGE PLANS COMMENCE D CASING TEST OTHER: perations (Clearly state all pertinent details, and give pertinent data th 35' of cement on top. Pump 25s on casing @ 2500' and pull casing. Pump 30sx cement plug from 4250'-435 Sing. Pump 50sx cement plug from 24 th dot -500'. Pump 10sx cement el and weld on steel cap. THE HOU FLU TO	PRILLING OPNS. PLUG AND ABANDONMENT AND CEMENT JOB ues, including estimated date of starting any proposed x cement plug from 7850'-8070'. Pump 25sx cement plug 6135'-6250'. 0'. Cut 8-5/8" intermediate casing 50'-2550'. WOC and tag plug. c surface plug. Cut casing off COMMAISSION MUS: BE NOTIFD 24 UPS PRIOR TO THE C AND ADD ADD ADD CUSS PRIOR TO THE C AND BE APPROVED.	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed O work) SEE RULE 1103. Set CIBP @ 10,275' w Cut 5-1/2" productio WOC and tag plug. P @ 2500' and pull cas Pump 70sx cement plu 3' below ground leve	PLUG AND ABANDON X REMEDIAL WO CHANGE PLANS COMMENCE D CASING TEST OTHER: perations (Clearly state all pertinent details, and give pertinent data th 35' of cement on top. Pump 25s on casing @ 2500' and pull casing. Pump 30sx cement plug from 4250'-435 Sing. Pump 50sx cement plug from 24 th g from 400'-500'. Pump 10sx cement el and weld on steel cap. THE HOU FLU TO	PRILLING OPNS. PLUG AND ABANDONMENT AND CEMENT JOB	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed O work) SEE RULE 1103. Set CIBP @ 10,275' w Cut 5-1/2'' productio WOC and tag plug. P @ 2500' and pull cas Pump 70sx cement plu 3' below ground leve I hereby certify that the information above SIONATURE	PLUG AND ABANDON X REMEDIAL WO CHANGE PLANS COMMENCE D CASING TEST OTHER: perations (Clearly state all pertinent details, and give pertinent data th 35' of cement on top. Pump 25s on casing @ 2500' and pull casing. Pump 30sx cement plug from 4250'-435 Sing. Pump 50sx cement plug from 24 th dot -500'. Pump 10sx cement el and weld on steel cap. THE HOU FLU TO	PRILLING OPNS. PLUG AND ABANDONMENT AND CEMENT JOB ues, including estimated date of starting any proposed x cement plug from 7850'-8070'. Pump 25sx cement plug 6135'-6250'. 0'. Cut 8-5/8" intermediate casing 50'-2550'. WOC and tag plug. c surface plug. Cut casing off COMMAISSION MUS: BE NOTIFD 24 UPS PRIOR TO THE C AND ADD ADD ADD CUSS PRIOR TO THE C AND BE APPROVED.	

	State of New J	forios	
Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATI P.O. Box 2	ON DIVISION	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088			30-025-23266
DISTRICT III			5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
			0G-5217
SUNDRY NOTIO	CES AND REPORTS ON WE	ELLS	
DIFFERENT MESERY	VOIN. USE "APPLICATION FOR P	ERMIT"	7. Lease Name or Unit Agreement Name
1. Type of Well:	101) FOR SUCH PROPOSALS.)		New Mexico "R" State
OE GAS WELL X WELL	OTHER		
2. Name of Operator			8. Well No.
Headington Oil Company 3. Address of Operator			2
-	- 1100 D-11 m		9. Pool name or Wildcat
7557 Rambler Road, Suite 4. Well Location	e 1100, Dallas, Texas	75231	Cerca Upper Penn
Unit Letter <u>H</u> : 2129	Feet From The North	Line and 660	Feet From The Lin
			Feet From The Last Lin
Section 33	Township 13S R 10. Elevation (Show whether	ange 34E I	NMPM Lea County
		0 [†] GR	
11. Check A	ppropriate Box to Indicate		aport or Other Date
NOTICE OF INTE	ENTION TO:		SEQUENT REPORT OF:
	PLUG AND ABANDON X	REMEDIAL WORK	
	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
_			PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEI	
		CASING TEST AND CEN	
DTHER:		CASING TEST AND CEN	
12. Describe Proposed or Completed Operation work) SEE RULE 1103.		CASING TEST AND CEN OTHER: ad give pertinent dates, includi	MENT JOB
DTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. Set CIBP @ 10,275' with Cut 5-1/2" production ca	35' of cement on top. sing @ 2500' and pull 30sx cement plug from Pump 50sx cement pl om 400'-500' Pump 1	CASING TEST AND CEN OTHER: of give pertinent dates, includit Pump 25sx ceme casing. Pump 2 4250'-4350'. C	MENT JOB
DTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. Set CIBP @ 10,275' with Cut 5-1/2" production ca. WOC and tag plug. Pump @ 2500' and pull casing. Pump 70sx cement plug from 3' below ground level and	35' of cement on top. sing @ 2500' and pull 30sx cement plug from Pump 50sx cement pl om 400'-500'. Pump 1 d weld on steel cap.	CASING TEST AND CEN OTHER: nd give pertinent dates, includi Pump 25sx ceme casing. Pump 2 4250'-4350'. C ug from 2450'-25. Osx cement surface 'HE HOU FILS	MENT JOB
DTHER:	35' of cement on top. sing @ 2500' and pull 30sx cement plug from Pump 50sx cement pl om 400'-500'. Pump 1 d weld on steel cap.	CASING TEST AND CEN OTHER: nd give pertinent dates, includi Pump 25sx ceme casing. Pump 2 4250'-4350'. C ug from 2450'-25. Osx cement surface MOU FILS TO	MENT JOB
DTHER:	35' of cement on top. sing @ 2500' and pull 30sx cement plug from Pump 50sx cement pl om 400'-500'. Pump 1 d weld on steel cap.	CASING TEST AND CEN OTHER: nd give pertinent dates, includi Pump 25sx ceme casing. Pump 2 4250'-4350'. C ug from 2450'-25. Osx cement surface 'HE HOU FILS	MENT JOB
DTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103. Set CIBP @ 10,275' with Cut 5-1/2" production ca. WOC and tag plug. Pump @ 2500' and pull casing. Pump 70sx cement plug from 3' below ground level and below ground level and thereby certify that the information above is true and SKONATURE	35' of cement on top. sing @ 2500' and pull 30sx cement plug from Pump 50sx cement pl om 400'-500'. Pump 1 d weld on steel cap.	CASING TEST AND CEN OTHER: nd give pertinent dates, includi Pump 25sx ceme casing. Pump 2 4250'-4350'. C ug from 2450'-25. Osx cement surface MOU FILS TO	MENT JOB
DTHER:	35' of cement on top. sing @ 2500' and pull 30sx cement plug from Pump 50sx cement pl om 400'-500'. Pump 1 d weld on steel cap. complete to the best of my knowledge and the Marren	CASING TEST AND CEN OTHER: Market give pertiment dates, includit Pump 25sx ceme casing. Pump 2 4250'-4350'. C ug from 2450'-25 Osx cement surfat Solution Figure IQ Solief. E. R.E.S. Coordina	MENT JOB

てい