

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole</u>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
<u>McGrath & Smith, Inc.</u>		<u>Markham</u>
3. Address of Operator		9. Well No.
<u>418 Building of the Southwest, Midland, Texas 79701</u>		<u>1</u>
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>West</u> LINE AND <u>2150</u> FEET FROM		<u>Wildcat</u>
THE <u>South</u> LINE, SECTION <u>23</u> TOWNSHIP <u>12-S</u> RANGE <u>37-E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
<u>GL 3892 KB 3904</u>		<u>Lea</u>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 6-27-70. Drld. 17 1/2 hole to 352'. Cmt'd. 13 3/8-61# csg. at 352' with 325 sx. Circ. 20 bbls. cmt. Plug down 8:45 am, 6-28-70. WOC 18 hrs. Tstd. 13 3/8 to 600 psi - OK. Drld. 11" hole to 4500'. Cmt'd. 8 5/8-24 & 32# csg. at 4500' with 450 sx. Plug down 7:00 am, 7-4-70. WOC 18 hrs. Tstd 8 5/8 to 1000 psi - OK. Drld. 7 7/8 hole to TD 11600'. Reached TD on 8-10-70. Ran logs. Propose to P & A as follows: Spot cmt. plugs 35 sx. at 11,600, 25 sx. top Penn, 25 sx. top WC, 25 sx. top Abo, 25 sx top Glor, 25 sx. across base of 8 5/8 at 4500', 25 sx. on 8 5/8 stub, 25 sx. across base of 13 3/8 at 352', 10 sx. in top 13 3/8 from 0-20'. Install DHM.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. Taylor</u>	TITLE <u>Sup't.</u>	DATE <u>8-13-70</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>[Signature]</u>	DATE <u>8-13-70</u>
CONDITIONS OF APPROVAL, IF ANY:		