

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-24031	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. E-5765	
7. Lease Name or Unit Agreement Name West Tres Papalotes Pen Unit	
8. Well No. 31-2 312	9. Pool name or Wildcat Tres Papalotes Penn West

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Permian Resources, Inc. dba Permian Partners, Inc.	
3. Address of Operator P. O. Box 590 Midland, TX 79702	
4. Well Location Unit Letter <u>I</u> : <u>2080</u> Feet From The <u>South</u> Line and <u>560</u> Feet From The <u>East</u> Line Section <u>31</u> Township <u>14S</u> Range <u>34E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4145 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 10,250' w/35' cmt. on top using wireline dumpbailer.
2. Displace well w/9.5 ppg. salt mud.
3. Spot 100' plug from 7000-6900'.
4. Cut 5-1/2" csg. @ 5500' and POH.
5. Spot 100' plug from 5500-5400' in csg. stub.
6. Spot 100' plug from 4260-4160' (8-5/8 shoe plug).
7. Cut 8-5/8 csg. @ 1500' and POH.
8. Spot 100' plug from 1500-1400' in csg. stub.
9. Spot 100' plug from 373-273' (12-3/4 surface shoe plug).
10. Spot 10 sxs. @ surface.
11. Weld on cap & install dry hole marker.

THIS NOTICE OF INTENTION TO
PLUG AND ABANDON
IS BEING SUBMITTED TO THE
DISTRICT SUPERVISOR

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randy Bruno TITLE Production Manager DATE 11/21/97
TYPE OR PRINT NAME Randy Bruno TELEPHONE NO. 915/685-0113

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JCT

dp