

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. NM 3352	
SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Mewbourne Oil Company	8. Farm or Lease Name Shell "A" State
3. Address of Operator P. O. Box 7698, Tyler, TX 75711	9. Well No. 1
4. Location of Well UNIT LETTER <u>H</u> <u>2080</u> FEET FROM THE <u>North</u> LINE AND <u>560</u> FEET FROM THE <u>East</u> LINE, SECTION <u>30</u> TOWNSHIP <u>14-S</u> RANGE <u>34-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Tres Papalotes-West
15. Elevation (Show whether DF, RT, GR, etc.) 4143 GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
---	---	---	---

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Will plug as follows:

Set Cast Iron Plug at top perforations - 10,390', with 35' cement on top.  
 100' - 50' in and 50' out at the stub of 4-1/2"  
 100' - Top Abo at 7964'.  
 100' - Top Glorietta 5900'.  
 100' - 50' in and 50' out 8-5/8" shoe.  
 100' - 50' in and 50' out 8-5/8" stub  
 100' - Top of Salt 1950'.  
 100' - 50' in and 50' out at the surface pipe shoe.  
 10 sacks at the top with marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Marjorie Lotz</u> Date Signed By <u>Marjorie Lotz</u> APPROVED BY <u>Don J. S. V.</u> CONDITIONS OF APPROVAL, IF ANY:	TITLE <u>Production Clerk</u> DATE <u>9/29/78</u> TITLE <u></u> DATE <u>OCT 4 1978</u>
--	---