

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-24228
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Samedan - Lowe SWD
8. Well No.	#1-H "SWD 382" #1
9. Pool name or Wildcat	None

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER SWD Well	
2. Name of Operator Samedan Oil Coporation	
3. Address of Operator 10 Desta Drive, Suite 240 East, Midland, Texas 79705	
4. Well Location Unit Letter <u>H</u> : <u>1986</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>3</u> Township <u>13-S</u> Range <u>37-E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Spot 30 sacks of cement at 12,000' W.O.C. No tag
- 2) Respot 30 sacks of cement at 12,000' W.O.C. tag cement plug at 11,720'
- 3) Load hole w/mud
- 4) Spot 25 sacks of cement at 9605'
- 5) Spot 25 sacks of cement at 5700'
- 6) Spot 45 sacks of cement at 4588' W.O.C. tag cement plug at 4443'
- 7) Spot 30 sacks of cement at 2290'
- 8) Spot 20 sacks of cement at surface and set up P.A. marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Raymond Maldonado TITLE Supervisor DATE 11-11-92

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE MAR 16 1993

CONDITIONS OF APPROVAL, IF ANY:

E