NO. OF COPIES RECEI	VED	i			<i>~</i> 's		
	<del></del>					Form C-103	
DISTRIBUTION						Supersedes C-102 and (	
SANTA FE		N	IEM WEXICO OIT CO	INSERVATION C	COMMISSION	Effective 1	
FILE							···
U.S.G.S.						5a. Indicate Ty	• –
LAND OFFICE						State	Fee XX
OPERATOR						5, State Oil & C	Gas Lease No.
<del></del>							<del>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</del>
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)							
1, 01L	GAS WELL	OTHER.	Dry			7. Unit Agreem	ent Name
2. Name of Operator						8. Farm or Lea	se Name
Tom L. Ingram						Markham	
3. Address of Operator						9. Well No.	<del></del>
	, Roswe	11, NM 8820	1			1	
4. Location of Well	1.	1980	ET FROM THE South		660	SW Glad	ool, or Wildcat Devonian
UNIT LETTER		TOO FEI	ET PROM THE	LINE AND	PEET FR	TITITI MOI	mmm
THE West	LINE, S	ECTION23	TOWNSHIP	RANGE _	37E	PM. (())	
	THIII.	15.	. Elevation (Show wheth	her DF, RT, GR, e	tc.)	12. County	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
			3894 GR		•	Lea	
16.	Che	alı Annanai a					
N		F INTENTION		Nature of No	otice, Report or ( SUBSEQUE	Other Data INT REPORT OF	₹:
PERFORM REMEDIAL WO TEMPORARILY ABANDON PULL OR ALTER CASING	OTICE O			REMEDIAL WOLCOMMENCE DR	SUBSEQUE	NT REPORT OF	ERING CASING  AND ABANDONMENT XX
PERFORM REMEDIAL WO	OTICE O		TO:	REMEDIAL WO	SUBSEQUE	NT REPORT OF	ERING CASING
PERFORM REMEDIAL WO TEMPORARILY ABANDON PULL OR ALTER CASING	OTICE O	FINTENTION	TO:	REMEDIAL WOLLD COMMENCE DR CABING TEST	SUBSEQUE	NT REPORT OF	ERING CASING  G AND ABANDONMENT XX
PERFORM REMEDIAL WO TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  17. Describe Proposed work) SEE RULE	or Complete iros.  P & A 100   p 100   p	as follows: lug @ 12386 lug @ 9500- lug @ 7750-	TO:  PLUG AND ABANDON  CHANGE PLANS  Arly state all pertinent of the perti	REMEDIAL WOLLD COMMENCE DR CABING TEST	SUBSEQUE	NT REPORT OF	ERING CASING  G AND ABANDONMENT XX
PERFORM REMEDIAL WO TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  17. Describe Proposed work) SEE RULE	or Complete 1 100	as follows: lug @ 12386 lug @ 7750- lug @ 5800- lug @ 4450-	PLUG AND ABANDON CHANGE PLANS  CHANGE PLANS  arly state all pertinent of 486 9600 7850 5900 -4550	REMEDIAL WOLLD COMMENCE DR CABING TEST	SUBSEQUE	NT REPORT OF	ERING CASING  G AND ABANDONMENT XX
PERFORM REMEDIAL WO TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  17. Describe Proposed work) SEE RULE	or Complete 1703.  P & A 100' p 100' p 100' p 100' p Mud us Shot 8 50 sx. 60 sx. 10 sx.	as follows: lug @ 12386 lug @ 9500- lug @ 7750- lug @ 5800- lug @ 4450- led between -5/8" csg. ( plug @ 117 plug @ 37 plug @ 37	TO:  PLUG AND ABANDON CHANGE PLANS  CHANGE PLANS  - 486 9600 7850 5900 -4550 plugs. @ 1200' and pu 4-1274 5-475	REMEDIAL WOLLD COMMENCE DR CABING TEST OTHER DETAILS, and give published	SUBSEQUE	NT REPORT OF	ERING CASING  G AND ABANDONMENT XX
PERFORM REMEDIAL WOTEMPORARILY ABANDON PULL OR ALTER CASING OTHER  17. Describe Proposed work) SEE RULE 7-22-73	or Complete fros.  P & A 100' p 100' s 100 s 50 sx 60 sx 10 sx Erecte	as follows: lug @ 12386 lug @ 9500- lug @ 5800- lug @ 4450- lug @ 4450- lug @ 117 plug @ 117 plug @ 37 plug @ 37	TO:  PLUG AND ABANDON CHANGE PLANS  CHANGE PLANS  - 486 9600 7850 5900 -4550 plugs. @ 1200' and pu 4-1274 5-475 0- 15	REMEDIAL WOLLD COMMENCE DR CABING TEST OTHER	SUBSEQUE	NT REPORT OF	ERING CASING
PERFORM REMEDIAL WOTEMPORARILY ABANDON PULL OR ALTER CASING OTHER  17. Describe Proposed work) SEE RULE 7-22-73	or Complete fros.  P & A 100' p 100' s 100 s 50 sx 60 sx 10 sx Erecte	as follows: lug @ 12386 lug @ 9500- lug @ 5800- lug @ 4450- lug @ 4450- lug @ 117 plug @ 117 plug @ 37 plug @ 37	TO:  PLUG AND ABANDON  CHANGE PLANS  - 486  9600  7850  5900  -4550  plugs.  @ 1200' and pu 4-1274  5-475  0- 15  Mud laden brin	REMEDIAL WOLLD COMMENCE DR CABING TEST OTHER	SUBSEQUE	NT REPORT OF	ERING CASING  G AND ABANDONMENT XX
PERFORM REMEDIAL WOTEMPORARILY ABANDON PULL OR ALTER CASING OTHER  17. Describe Proposed work) SEE RULE 7-22-73	or Complete fros.  P & A 100' p 100' s 100 s 50 sx 60 sx 10 sx Erecte	as follows: lug @ 12386 lug @ 9500- lug @ 5800- lug @ 4450- lug @ 4450- lug @ 117 plug @ 117 plug @ 37 plug @ 37	TO:  PLUG AND ABANDON  CHANGE PLANS  - 486  9600  7850  5900  -4550  plugs.  @ 1200' and pu 4-1274  5-475  0- 15  Mud laden brin	REMEDIAL WOLLD COMMENCE DR CABING TEST OTHER	SUBSEQUE	NT REPORT OF	ERING CASING  G AND ABANDONMENT XX

Operator

TITLE\_

CONDITIONS OF APPROVAL, IF ANY

DATE\_\_\_\_\_

DATE 1/25/74