NO. OF COPICS RECEIVED		Form C-103 Supersedes Old
DISTRIBUTION	· · · · · · · · · · · · · · · · · · ·	C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	<del>-   </del>	5g, Indicute Type of Lease
U.S.G.S.		State X Fee
LAND OFFICE		5. State Oil & Gas Leaso No.
OPERATOR		v 1413
	SUNDRY NOTICES AND REPORTS ON WELLS	
LOO NOT USE THIS P	DRO FOR PROPERSALS TO TRILL OR TO CLEPEN OR PLUG PACK TO A DIFFERENT RESERVOIR.  E "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPUBLES.)	7, Unit Agreement Name
1. OU (V) 6A	,	
WELL A		8. Farm of Lease Hame
2. Name of Operator M & W, OF	LOVINGTON, INC.	CITIES SERVICE STAT
3. Address of Operator		9. Well No.
BOX 922	LOVINGTON NM 88260 .	10. Field and Pool, or Wildeat
4. Lecution of Well		
	1980 FEET FROM THE NORTH LINE AND 660 FEET FROM	HIGH PLAINS PENN
UNIT LETTER	71. 5	
WEST	LINE, SECTION TOWNSHIP RANGE D4 ENMPM.	
	15. Elevation (Show whether DF, RT, GR, etc.)	12, County
	4084 GL	LEA ((()))
VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
	Check Appropriate box To Material Material Transfer Subsequent	REPORT OF:
· NO I	ICE OF INTENTION TO	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABAHDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
7002 011 010	OTHER	
OTHER		
	Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
17. Describe Proposed or work) SEE RULE 110	2p over perc o 10 ///6/-/49, ////5//-5b/, ///.45/	7'-62,
1	7 SACKS CEMENT & (100') PLUG & 9700' TO 9801'.	
2. SET 1	n ninc a 9801'	
ろ、 TAGGE 4. RAN G	AMMA RAY DEPTH CONTROL LOG.  1 JSPF 9685'-98' 13 HOLES.  500 GAL. 15% HCL NE FE ACID.	•
5 PERF	1 USPF 9685'-98' 13 HOLES.	
5. PERF 6. SPOT	500 GAL. 15% HCL NE FE ACID.	
7. BREAK	DOWN FORMATION 3700#.	
8. PUMP	2500 GAL 15% HCL NE FE ACID WITH 2 BALL SEALERS	EVER 4 BBL.
U 10 T	OUT	
10. AVG.	INJ. RATE 3 BPM AVG. PRESSURE 4000#.	
11. SWAE	BB ACID BACK.	
12. PUT	BACK ON PUMP.	
	•	
	•	

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGHTO PRESIDENT DATE 6-10-85

ORIGINAL SPANSOR PROPERVISOR

OISTRICT I SUPERVISOR

TITLE PRESIDENT DATE 6-10-85