

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501Form C-103  
Revised 10-1-

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
NA	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry	7. Unit Agreement Name NA
2. Name of Operator OGR Operating Co., Inc.	8. Farm or Lease Name Seay State
3. Address of Operator 1140 Two First City Center, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 30 TOWNSHIP 12-S RANGE 34-E N.M.P.M.	10. Field and Pool, or Wildcat Hightower, East
15. Elevation (Show whether DF, RT, GR, etc.) 4217 G1	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

## 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

- Displace 5-1/2" csg with 10# brine mud containing 25#/bbl salt gel
- Spot 30sx plug @ 9130' to cover perms 9132'-9144' and Wolfcamp top @ 9052'
- Spot 25sx plug @ 5510 to cover Glorietta
- Spot 30sx plug @ 4150 to cover 8-5/8" shoe @ 4100' & top of San Andres @ 4030'  
~~WOC & tag plug~~
- Cut 5-1/2" csg @ 1500' & recover
- ~~Spot 25sx 1800' to cover top of salt~~
- Spot 35sx @ 1550' to cover 5-1/2" stub - WOC & tag plug
- Spot 50sx @ 380' to cover 12-3/4" shoe @ 330'. ~~WOC & tag plug~~
- Spot 10sx plug at surface
- Install dry hole marker & clean location

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mickey Dalton TITLE Vice President-Drlg & Prod DATE 3-20-86APPROVED BY Jerry Sexton TITLE DISTRICT SUPERVISOR DATE JUN 18 1986  
CONDITIONS OF APPROVAL ORIGINAL SIGNED BY JERRY SEXTON