

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. '30 025 26190
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator MERIT ENERGY COMPANY		6. State Oil & Gas Lease No. LG3333
3. Address of Operator 12222 MERIT DRIVE; DALLAS, TX 75251		7. Lease Name or Unit Agreement Name: STATE "17"
4. Well Location Unit Letter <u>F</u> : 1980 feet from the <u>NORTH</u> line and 1980 feet from the <u>WEST</u> line Section <u>17</u> Township <u>14S</u> Range <u>36E</u> NMPM <u>LEA</u> County <u></u>		8. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) GR 3962		9. Pool name or Wildcat AUSTIN; MISSISSIPPIAN (GAS)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐


OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

PLUGGING PROCEDURE:

- 1) SPOT 100' PLUG @ 5000' AND TAG.
- 2) SET CIBP @ +/- 4700'.
- 3) PERFORATE 50' BELOW INTERMEDIATE SHOE (4690').
- 4) SQUEEZE @ INTERMEDIATE CASING POINT (4640') AND TAG.
- 5) SPOT PLUG @ 1100' TO COVER SALT FORMATION.
- 6) SPOT PLUG (25 SX OR 100') AT SURFACE SHOE (396'). — TAG
- 7) SPOT 10 SX 60' FROM SURFACE.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bev Hatfield TITLE REGULATORY ANALYST DATE 5/22/02

Type or print name BEV HATFIELD Telephone No. (972) 455-9630

(This space for State use)

APPROVED BY GARY W. WINK DATE MAY 29 2002
Conditions of approval, if any: OC FIELD REPRESENTATIVE II/STAFF MANAGER