Submit 3 Copies to Appropriate

District Office

te of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I	P. O. Box 2		Well API NO.
P. O. Box 1980 Hobbs, NM 88240 Santa Fe, New Mexico 87504-2088			30-025-27259
DISTRICT II			5.Indicate Type or Lease
P. O. Drawer DD, Artesia, NM 88210			STATE FEE X
DISTRICT III			6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM	4 87410		
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			DUNCAN UNIT
1. Type of Well			- Benear our
OIL X GAS COTTER			8. Well No.
WELL WELL OTHER 2. Name of Operator			# 2
Harvey E. Yates Company			9. Pool name or Wildcat
3. Address of Operator			yω
P.O. Box 1933, Roswell, NM 88202 1-505-623-6601			AUSTIN PERMO PENN, NE
4. Well Location			HOSTIN I EMINO I ENTRY IVE
Unit Letter I	: 1,980 Feet From The	NORTH Line and	1,980 Feet From The WEST Line
Section	26 Townshij 13S	Range 35E	NMPM LEA County
	10. Elevation (Show	v whether DF, RKB, RT, GR, etc.) 4019.6' GR	
11. Check Appropriate Box to Indicat Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WO		X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CEMENT JO	ов
OTHER:		OTHER:	
12. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
work.) SEE RULE 1103			
ATTEMPT TO PERF TUBING @ APPROX. 9562 (JUST ABOVE RODS). THIS WILL REQUIRE GOING THRU STUCK TBG @ 7102'-8010' AND BACK IN TBG 5' BELOW TO GET DOWN TO ROD TOP.			
IF TUBING GOES ON VAC. THEN PUMP CEMENT TO PERFS & ACROSS CUT @ 8010' INTERVAL.			
IF TUBING DOES NOT GO ON VAC. THEN ATTEMPT TO PUMP CEMENT TO COVER CUT @ 8010' AND BACK TO TOP			
OF STUCK TBG @ 7102'.			
TAG CEMENT TO DETERMINE TOP.			
DETERMINE FREE POINT AND CUT CASING (EST. @ ABOUT 6500 TO 7000'). PULL & LAYDOWN CASING.			
PUMP 200' CEMENT PLUG (50' IN & 150' OUT) AT STUB. (TAG THIS PLUG). PUMP 100' CEMENT PLUG @ 5900' (YESO TOP).			
PUMP 150' CEMENT PLUG @ 4600' (ACROSS INTERM. SHOE @ 4515')			
PUMP 100' CEMENT PLUG @ 2100' (TOP OF ANHYD.)			
PUMP 100' CEMENT PLUG @ 400' (ACROSS SURFACE SHOE).			
PUMP 50' CEMENT PLUG @ SURFACE. CUT OFF AND INSTALL DRY HOLE MARKER.			
I hereby certify that the information a	bove is true and complete to the best of my knowledge at	d belief.	
	101	mary n DDOD MCD / EN	CINEED
TYPE OR PRINT NAME	RAY F. NOKES	TITLE PROD. MGR. / EN	TELEPHONE NO. 1-505-623-6601
	CHIGINAL SIGNED BY		1 DDD 110.1D 110. 1-300-020-0001
(This space for State use)	GARY WINK		APR 4 0 4000
Approved by	FIELD REP. II	Title	Date SEP 13 1996
Conditions of approval, if any:			

IS

,