

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
Post	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
South King (Devonian)	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator
Union Texas Petroleum Corporation
3. Address of Operator
4000 N. Big Spring, Suite 500
4. Location of Well
UNIT LETTER N 990 FEET FROM THE South LINE AND 1650 FEET FROM
West THE LINE, SECTION 1 TOWNSHIP 14-S RANGE 37-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
3831 GR.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	OTHER <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
OTHER Squeeze perforation & re-perforate <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
same zone.	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRUSU. Install BOP, POH with production equipment.
2. Run in hole with 4 3/4" bit and casing scraper to TD.
3. Run in hole with cement retainer and set retainer at 12580'±. Squeeze perforation 12,729' - 12,758' with 200 sx. Cl. "H" cement and 36 bbls. FLO-check.
4. Drill out cement retainer & cement and run bit to TD.
5. Pressure test casing to 1000# psi.
6. Perforate casing 12,729' to 12,750' w/4JSPF. Acidize perforation with 1000 gal 15% H Cl. NEFE.
7. Run submersible production pump and put well back on production.
8. RDSU and clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED William A. Higgins TITLE Regul. Compl. Coord. DATE 6-29-84  
ORIGINAL SIGNED BY GRAY SEXTON DATE JUL - 6 1984  
APPROVED BY GRAY SEXTON TITLE SUPERVISOR  
CONDITIONS OF APPROVAL, IF ANY: