STATE OF NEW MEXICO ENERGY AND MINIERALS DEPARTMENT

	T	
DISTRIBUTION		
BANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION

DISTRIBUTIO	OH		P. O. BO	X 2088		Revi	ised 10
BANTAFE		SAN	TA FE, NEW	MEXICO 87	501		
FILE				, #-		5a. Indicate Type of Lea	S.
U.S.G.S.						State 🔣	Fee 🗌
LAND OFFICE				•		5. State Oil & Gas Lease	e No.
OPERATOR						V-0108	1
SUNDRY NOTICES AND REPORTS ON WELLS [DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" IFORM C-1011 FOR SUCH PROPOSALS.)							
01L X	GAS WELL	OTHER-				7, Unit Agreement Name	
Name of Operator MWJ PRODUCING COMPANY						6. Form or Lease Name Baum 7 Stat	te
. Address of Operator					9. Well No.		
400 W. Illinois Suite 1100 Midland, Texas 79701					3		
Location of Well						10. Field and Pool, or W	/Hdcat
UNIT LETTER	H . 1	L980	Nort	h LINE AND	660 FEET FROM	Baum Upper Pe	mn nn
East		7	1 4	ς	33E-		
THE	LINE, SECTION	· + c	OWHSHIP	RANGE	NMPM.		
mmm	mm	TTTT LE Flower	ion (Show whether	DE RT CR etc		12. County	<i>HHHH</i>
		11/1/2 13. 514101			,	Lea	
711111111111111111111111111111111111111	77777777	77777	426				7777777
N	OTICE OF INT	• • •	To indicate N	ature of Notic	ce, Report or Ot SUBSEQUEN	REPORT OF:	
				·			
CAFORM REMEDIAL WOR EMPORARILY ABANDON ULL OR ALTER CABING OTHER			GE PLANS	REMEDIAL WORK COMMENCE DRILL CASING TEST AND OTHER	CEMENT JOS	ALTERING CAS PLUG AND ABA	HDONMENT X
EMPORARILY ABANDON ULL OR ALTER CABING OTHER		CHANG	GE PLANS	COMMENCE DRILL CASING TEST AND OTHER	CEMENT JOS	PLUG AND ABAI	HDOHMENT X
EMPORABILY ABANDON ULL OR ALTER CABING OTHER	or Completed Open	CHANG	GE PLANS	COMMENCE DRILL CASING TEST AND OTHER	CEMENT JOS		HDOHMENT X
OTHER Describe Proposed work) SEE RULE 1	or Completed Operators. Spt'd 25	CHANG	e all pertinent deta	COMMENCE ORILL CASING TEST AND OTHER ails, and give pert	CEMENT JOS	PLUG AND ABAI	any proposed
other	or Completed Operators. Spt'd 25 SD.	rations (Clearly state SX CMt plu	e all pertinent deta	commence drill casing test and otherails, and give pert	inens dases, including	PLUG AND ABAI	any proposed
other 12/3/88: 12/4/88: 12/5/88:	or Completed Oper 103. Spt'd 25 SD. Shot csg	rations (Clearly state sx cmt plu off @ 4000	e all pertinent deta	other 92' to 89	inens dases, including	PLUG AND ABAI	any proposed
OTHER	or Completed Operators. Spt'd 25 SD. Shot csg Shot csg	rations (Clearly state sx cmt plu off @ 4000 @ 4200', P	e all pertinent details from 90	commence or ill casing test and other ails, and give pert 92' to 89 d not com	inent dates, including 64' (tagged	estimated date of starting plug @ 8964'	any proposed
other 12/3/88: 12/4/88: 12/5/88:	or Completed Operators. Spt'd 25 SD. Shot csg Shot csg Spt'd 20	rations (Clearly state sx cmt plu off @ 4000 @ 4200', P sx cmt plu	e all pertinent deta g from 90 0', csg di 000H, LD c 1g from 60	commence drill casing test and other give pert 92' to 89 d not com sg. 00-5900',	inent dates, including 64' (tagged	PLUG AND ABAI	any proposed
OTHER	or Completed Operators. Spt'd 25 SD. Shot csg Shot csg Spt'd 20 50 sx cmt	rations (Clearly state sx cmt plu off @ 4000 @ 4200', P sx cmt plu t plug @ 42	e all pertinent details g from 90 cooh, LD codg from 60 cooh.	commence drill casing test and other give pert 92' to 89 d not com sg. 00-5900',	inent dates, including 64' (tagged e free. WOC 4 hrs	estimated date of starting plug @ 8964' & tagged plug	any proposed). Spt'd
OTHER	or Completed Operations. Spt'd 25 SD. Shot csg Shot csg Spt'd 20 50 sx cmt Tagged to	rations (Clearly state sx cmt plu off @ 4000 @ 4200', P sx cmt plu t plug @ 42	e all pertinent details from 90 cl, csg di POOH, LD clig from 60 clig	other sile pert and give pert 92' to 89 d not com sg. 00-5900', Spt'd 35	inens dases, including 64' (tagged e free. WOC 4 hrs sx cmt plu	estimated date of starting plug @ 8964'	any proposed). Spt'd
OTHER	or Completed Operation. Spt'd 25 SD. Shot csg Shot csg Spt'd 20 50 sx cmt Tagged to Spt'd 10	rations (Clearly state sx cmt plu off @ 4000 @ 4200', P sx cmt plu t plug @ 42	e all pertinent details from 90 cl, csg di POOH, LD clig from 60 clig	other sile pert and give pert 92' to 89 d not com sg. 00-5900', Spt'd 35	inens dases, including 64' (tagged e free. WOC 4 hrs sx cmt plu	estimated date of starting plug @ 8964' & tagged plug	any proposed). Spt'd
OTHER	or Completed Operators. Spt'd 25 SD. Shot csg Shot csg Spt'd 20 50 sx cmt Tagged to Spt'd 10 SD.	rations (Clearly state sx cmt plu off @ 4000 @ 4200', P sx cmt plu t plug @ 42	e all pertinent deta ag from 90 1', csg di 200H, LD c 1g from 60 130'. WOC 14060'.	other sile pert and give pert 92' to 89 d not com sg. 00-5900', Spt'd 35	inens dases, including 64' (tagged e free. WOC 4 hrs sx cmt plu	estimated date of starting plug @ 8964' & tagged plug	any proposed). Spt'd
OTHER	or Completed Operators. Spt'd 25 SD. Shot csg Shot csg Spt'd 20 50 sx cmt Tagged to Spt'd 10 SD.	off @ 4000 @ 4200', P sx cmt plu sx cmt plu plug @ 42 pp of plug sx cmt plu	e all pertinent deta ag from 90 1', csg di 200H, LD c 1g from 60 130'. WOC 14060'.	other sile pert and give pert 92' to 89 d not com sg. 00-5900', Spt'd 35	inens dases, including 64' (tagged e free. WOC 4 hrs sx cmt plu	estimated date of starting plug @ 8964' & tagged plug	any proposed). Spt'd
OTHER	or Completed Operators. Spt'd 25 SD. Shot csg Shot csg Spt'd 20 50 sx cmt Tagged to Spt'd 10 SD.	off @ 4000 @ 4200', P sx cmt plu sx cmt plu plug @ 42 pp of plug sx cmt plu	e all pertinent details g from 90 cooh, LD cooh, LD cooh, LD cooh, WOC 6 4060'. Ig from 50 cooh, ag from 50	other sile pert and give pert 92' to 89 d not com sg. 00-5900', Spt'd 35	inens dases, including 64' (tagged e free. WOC 4 hrs sx cmt plu	estimated date of starting plug @ 8964' & tagged plug	any proposed). Spt'd
OTHER	or Completed Operators. Spt'd 25 SD. Shot csg Shot csg Spt'd 20 50 sx cmt Tagged to Spt'd 10 SD.	off @ 4000 @ 4200', P sx cmt plu c plug @ 42 pp of plug sx cmt plu d dry hole	e all pertinent details g from 90 cooh, LD cooh, LD cooh, LD cooh, WOC 6 4060'. Ig from 50 cooh, ag from 50	other sile pert and give pert 92' to 89 d not com sg. 00-5900', Spt'd 35	inens dases, including 64' (tagged e free. WOC 4 hrs sx cmt plu	estimated date of starting plug @ 8964' & tagged plug	any proposed). Spt'd
The proposed work) SEE RULE 1 12/3/88: 12/4/88: 12/5/88: 12/6/88: 12/8/88: 12/9/88!	or Completed Operators. Spt'd 25 SD. Shot csg Shot csg Spt'd 20 50 sx cmt Tagged to Spt'd 10 SD.	off @ 4000 @ 4200', P sx cmt plu c plug @ 42 pp of plug sx cmt plu d dry hole	e all pertinent details g from 90 cooh, LD cooh, LD cooh, LD cooh, WOC 6 4060'. Ig from 50 cooh, ag from 50	other sile pert and give pert 92' to 89 d not com sg. 00-5900', Spt'd 35	inens dases, including 64' (tagged e free. WOC 4 hrs sx cmt plu	estimated date of starting plug @ 8964' & tagged plug	any proposed). Spt'd
The proposed work) SEE RULE 1 12/3/88: 12/4/88: 12/5/88: 12/6/88: 12/8/88: 12/9/88!	or Completed Operators. Spt'd 25 SD. Shot csg Shot csg Spt'd 20 50 sx cmt Tagged to Spt'd 10 SD.	off @ 4000 @ 4200', P sx cmt plu c plug @ 42 pp of plug sx cmt plu d dry hole	e all pertinent details g from 90 cooh, LD cooh, LD cooh, LD cooh, WOC 6 4060'. Ig from 50 cooh, ag from 50	other sile pert and give pert 92' to 89 d not com sg. 00-5900', Spt'd 35	inens dases, including 64' (tagged e free. WOC 4 hrs sx cmt plu	estimated date of starting plug @ 8964' & tagged plug	any proposed). Spt'd
The proposed work) SEE RULE 1 12/3/88: 12/4/88: 12/5/88: 12/6/88: 12/8/88: 12/9/88!	or Completed Operators. Spt'd 25 SD. Shot csg Shot csg Spt'd 20 50 sx cmt Tagged to Spt'd 10 SD.	off @ 4000 @ 4200', P sx cmt plu c plug @ 42 pp of plug sx cmt plu d dry hole	e all pertinent details g from 90 cooh, LD cooh, LD cooh, LD cooh, WOC 6 4060'. Ig from 50 cooh, ag from 50	other sile pert and give pert 92' to 89 d not com sg. 00-5900', Spt'd 35	inens dases, including 64' (tagged e free. WOC 4 hrs sx cmt plu	estimated date of starting plug @ 8964' & tagged plug	any proposed). Spt'd