

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-025-28102
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-2043
7. Lease Name or Unit Agreement Name West Tres Papalotes Pen Unit
8. Well No. 313
9. Pool name or Wildcat Tres Papalotes Penn West

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Permian Resources, Inc. dba Permian Partners, Inc.	
3. Address of Operator P. O. Box 590 Midland, TX 79702	
4. Well Location Unit Letter <u>A</u> : <u>1160</u> Feet From The <u>North</u> Line and <u>560</u> Feet From The <u>East</u> Line Section <u>31</u> Township <u>14S</u> Range <u>34E</u> NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4144.3 GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
 PULL OR ALTER CASING ☐  
 OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
 CASING TEST AND CEMENT JOB ☐  
 OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 10,300 w/35' cmt. on top using wireline dumpbailer.
2. Displace well with 9.5 ppg. salt mud.
3. Spot 100' plug from 7000-6900'.
4. Spot 100' plug from 4320-4220' (8-5/8 shoe plug).
5. Cut 4-1/2" csg. @ 1100' and POH.
6. Spot 100' plug from 1100'-1000' in casing stub.
7. Spot 100' plug from 400-300' (12-3/4 surface shoe plug).
8. Spot 100 sxs. @ surface.
9. Weld on cap & dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE OWS TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Randy Bruno TITLE Production Manager DATE 11/21/97

TYPE OR PRINT NAME Randy Bruno

TELEPHONE NO. 915/685-0113

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS  
DISTRICT SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

SCJ