

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

IL CONSERVATION DIVISIO.
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
Name of Operator Marks & Garner Production Company		5. State Oil & Gas Lease No.
Address of Operator c/o Oil Reports & Gas Services, Inc Box 755, Hobbs, NM 88241		7. Unit Agreement Name
Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM.		8. Farm or Lease Name Huber "A" State Ltd
		9. Well No. 1
		10. Field and Pool, or Wildcat Lazy J Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4187.7 GR		12. County Lea

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to plug for abandonment as Follows:
 Set cast iron bridge plug at 9750 & cap with 10 sacks cement
 Spot 100' cement plug 6500 to 6600
 Cut & pull 5 1/2" casing from 4000
 Spot 100' cement plug 3950 to 4050
 Spot 100' cement plug 335 to 435
 Set 20 sack plug at surface
 Mud between all plugs
 Erect surface marker & clean location

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Monica Heller TITLE Agent DATE 6/4/86
 ORIGINAL SIGNED BY JERRY SEXTON
 DISTRICT 1 SUPERVISOR
 PROVED BY _____ TITLE _____ DATE JUN 5 1986
 CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUN 4 1986
O.C.D.
HOBBS OFFICE