

State of New Mexico  
Energy, Minerals and Natural Resources Department

DISTRICT I

P.O. Box 1980, Hobbs NM 88240

DISTRICT II

P.O. Drawer DD, Artesia NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28138
5. Indicate Type of Lease	State <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG-2670
7. Lease Name or Unit Agreement Name	DOVE VK STATE
8. Well No.	2
9. Pool Name or Wildcat	LAZY J PENN

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well  
OIL  GAS   
WELL  WELL  OTHER

2. Name of Operator  
Yates Petroleum Corporation

3. Address of Operator  
105 South 4th., Artesia, NM 88210

4. Well Location  
Unit Letter E : 1980 Feet From The NORTH Line and 660 Feet From The WEST Line  
Section 3 Township T14S Range R33E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
4234.5' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK  PLUG AND ABANDON   
TEMPORARILY ABANDON  CHANGE PLANS   
PULL OR ALTER CASING   
OTHER \_\_\_\_\_

SUBSEQUENT REPORT OF:

REMEDIAL WORK  ALTERING CASING   
COMMENCE DRILLING OPNS.  PLUG AND ABANDONMENT   
CASING TEST AND CEMENT JOB   
OTHER Production casing & cement

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Yates Petroleum Corporation respectfully requests permission to plug & abandon as follows:

- MIRU PU & plugging equipment.
- Pull rods, pump, tubing, & anchor. Production records show gas anchor @ 9497'.
- Set CIBP @ 9250' & cap w/ 35' of cement.
- Freepoint 5-1/2" casing. Cut & pull 5-1/2" casing. TOC is 6760' per cement bond log.
- GIH w/ tubing open ended to 7750'; load hole w/ salt gel plugging mud.
- Spot 25 sk cement plug across Abo top (7705') from 7750-7650'.
- Pull up & spot a 35 sk cement plug across 5-1/2" casing stub ( @ 6600'+-). Pull up, WOC & tag plug at least 50' above stub. If no tag, respot plug, WOC, & tag.
- Pull up & spot 35 sk cement plug across Glorieta top - 5527'.
- Pull up & spot 35 sk cement plug across 8-5/8" casing shoe - 4200'. WOC & tag this plug @ 4150' or higher. If no tag, respot plug, WOC, & tag.
- Pull up & spot 35 sk plug across 13-3/8" shoe depth - 462'.
- Set a 15 sk plug at surface & install regulation abandonment marker.

Thereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Anna Clark TITLE Operations Technician DATE 3/20/02  
TYPE OR PRINT NAME \_\_\_\_\_ TELEPHONE NO. 505-748-1471

(This space for State Use)  
APPROVED BY \_\_\_\_\_ ORIGINAL SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY \_\_\_\_\_  
OC FIELD REPRESENTATIVE II/STAFF MANAGER

S  
P  
S

