

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Walter Oil & Gas Corporation 3. Address of Operator 240 Main Bldg., 1212 Main Street, Houston, Texas 77002 4. Location of Well UNIT LETTER <u>F</u> <u>1890</u> FEET FROM THE <u>North</u> LINE AND <u>2105</u> FEET FROM THE <u>West</u> LINE, SECTION <u>26</u> TOWNSHIP <u>12 S</u> RANGE <u>37 E</u> N.M.P.M. 15. Elevation (Show whether DF, RT, GR, etc.) 3882.5' GL	7. Unit Agreement Name N/A 8. Farm or Lease Name D. P. Peck Estate 9. Well No. 1 10. Field and Pool, or Wildcat Gladiola, S.W. 12. County Lea
--	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Date Started: 9/17/85 CASING: 13-3/8" @ 392' MW: 9.6 ppg
 Date Completed: 9/20/85 9-5/8" @ 4465' Cement: 15.6 ppg
 TD: 12,303' 5-1/2" @ 9860' Yield: 1.18 cu.ft./sx.
 PBTD: 9,820' Cut off 5-1/2" @ 5120'

Plugging Operations:

- Set CIBP @ 9650'. Dump 35' (5 sx) H Neat on top of plug.
- Set 15 sx H Neat @ 6662'. Set 35 sx H + 2% CC @ 5170'. Tag plug @ 5075'.
- Set 50 sx H + 2% CC @ 4510'. Tag plug @ 4518'.
- Set 35 sx H Neat @ 2000'. Set 15 sx H Neat @ 10' to surface.
- Removed equipment and cleared location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kim Burkett TITLE Regulatory Coordinator DATE 10/5/85
Kim Burkett
 APPROVED BY Eddie W. Seay TITLE Oil & Gas Inspector DATE MAY 1 - 1986
 CONDITIONS OF APPROVAL, IF ANY: