STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	1	
DISTRIBUTION		
SANTA FE	\top	
FILE		
U.S.G.S.]	
LAND OFFICE	1	
CPERATOR	7	1

CONDITIONS OF APPROVAL, IF ANY

etterior ...

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103

SANTA FE	CARITA EE NEW MEYICO 97501		Revised 10-1-/8	
FILE	SANTA FE, NEW MEXICO 87501 Sa, Indicate Type of Lease		La Indicate Type of Lease	
V.S.G.S.				
LAND OFFICE			State X Fee	
OPERATOR	•	•	5. State Oil & Gas Lease No.	
<u></u>	•		LG 2414	
CI NICO	A NOTICES AND DEPORTS ON	LWELLE		
IDO NOT USE THIS FORM FOR PROP	Y NOTICES AND REPORTS ON	BACK TO A DIFFERENT RESERVOIR.		
USE "APPLICATI	ON FOR PERMIT -" (FORM C-101) FOR SU	ICH PROPOSALS.]	7, Unit Agreement Name	
l. GAS []	`		7, Om Agreement Plant	
MELL X MELL	OTHER-			
2. Name of Operator			8. Farm or Lease Name	
Yates Petroleum (Corporation		Chalupa AAD State	
J. Address of Operator			9. Well No.	
207 South 4th St., Artesia, NM 88210			4	
			10. Field and Pool, or Wildcat	
4. Location of Well			Saunders Permo Upper Pen	
UNIT LETTER M 330 FEET FROM THE SOUTH LINE AND 330 FEET FROM			3adiders refino opper real	
			MILLINI MILLINI MARKATAN MARKA	
West	<u> </u>	14S BANGE 33E NMP		
THE West LINE, SECTION 13 TOWNSHIP 14S RANGE 33E NMPM.				
	15. Elevation (Show whether	er DF, RT, GR, etc.)	12. County	
	4180.9' GR	•	Lea	
	4100.3 GR		Lea (////////////////////////////////////	
16. Check A	Appropriate Box To Indicate	Nature of Notice, Report or C	ther Data	
	TENTION TO:		NT REPORT OF:	
		REMEDIAL WORK	ALTERING CASING	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	11 ====================================	=	
TEMPORARILY ABANDON	_ _	COMMENCE DRILLING OPNS.	PLUG AND ASANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST ONA TEST SHIEAD	are same and the s	
	·	ОТИЕЯ		
OTHER Set retainer and	d squeeze perfs & . X] [
perforate,	treat			
	erations (Clearly state all pertinent de	etails, and give pertinent dates, includi	ng estimated date of starting any proposed	
work) SEE RULE 1 103.				
Propose to pull prod	luction equipment.			
Set cement retainer on wireline @9980'.				
Squeeze perfs 10002-	-10024'.			
Perforate 9929-57' w/14 .42" holes.				
Acidize perfs 9929-57' w/3000 gals 15% NEFE acid and ball sealers.				
Swab back load and hang back on pump for test.				
Swab back toad and i	lang back on pump for te	est.		
	•			
			•	
18. I hereby certify that the information	above is true and complete to the best	of my knowledge and belief.		
	2			
4	1), 11	Production Supervisor	9AVE 4-3-86	
BIGHT WILL E	LOTULIA TITLE	120ddccton bupervisor	DATE 4-3-00	
	7			
ORIGINAL SIGNED B	IY JERRY CEVEZ.		APR 8 - 1986	
APPROVED BY DISTRICT ! SE	IPERVISOR TITLE		PATE ME 17 0 1300	
	·· =n 1130K			

TORRESCONDER SON

ALL SERVICES OF A LICENSE OF A