

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-2265

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Tahoe Oil & Cattle Company 3. Address of Operator 4402 West Industrial - Midland, Texas 79703 4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 11 TOWNSHIP 14 RANGE 33 NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 4196' GR	7. Unit Agreement Name 8. Farm or Lease Name Tahoe WA State 9. Well No. 1 10. Field and Pool, or Wildcat Saunders Permo Upper Penn. 12. County Lea
--	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Completion <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- Run Gamma Ray Collar Log from (+/-)10,000' to 9400'.
- Perforate Bough "D" Zone with select fire casing gun from 9977' to 9983'.
- Acidize w/2000 gal 15% Fe acid, swab and test. If commercial put on rod pump and production.
- If non-commercial set a bridge plug.
- Perforate Bough "B" and "C" Zones, acidize and test for production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (X) J. A. Freeman TITLE Petroleum Engineer DATE 10-19-87

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY _____ TITLE _____ DATE NOV 22 1987

CONDITIONS OF APPROVAL, IF ANY: