

ISTRICT I
O. Box 1980, Hobbs, NM 88240
ISTRICT II
O. Drawer DD, Artesia, NM 88210
ISTRICT III
000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30484 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-2265
7. Lease Name or Unit Agreement Name Tahoe WA State
8. Well No. 3
9. Pool name or Wildcat Saunders Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

Name of Operator
YATES PETROLEUM CORPORATION

Address of Operator
105 South 4th St., Artesia, NM 88210

Well Location
Unit Letter B : 990 Feet From The North Line and 1980 Feet From The East Line

Section 11 Township 14S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
WILL OR ALTER CASING ☐
OTHER: Add perforations ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to perforate and acidize additional and existing Bough AB, C & D zones as follows:

1. POOH w/tubing, packer and pump. Packer set at 9688'.
2. Perforate 9765-9827' (Bough AB) w/10 holes (1 SPF) as follows: 9765, 9766, 9779, 81, 83, 9809, 9811, 9813, 9824 & 9827'; 9872-9901' (Bough C) w/4 holes (1 SPF) as follows: 9872, 74, 91, 9901; 9923-9952' (Bough D) w/7 holes (1 SPF) as follows: 9923, 28, 31, 43, 44, 51 & 9952'.
3. RIH w/tubing, packer & RBP. Set RBP at 9975'+/- and test. Spot 1 bbl 15% NEFE acid across perforations 9871-9952'. Pull packer to 9850'+/-. Acidize perforations 9871-9952' w/5000 gallons 15% NEFE acid w/scale inhibitor and ball sealers.
4. Set RBP at 9850'+/- and test. Spot 1 barrel 15% NEFE acid across perforations 9765-9828'. Pull packer to 9740'+/-. Acidize perforations 9765-9828' w/5000 gallons 15% NEFE acid w/scale inhibitor & ball sealers.
5. Set RBP at 9975'+/- and packer at 9740'+/-. Swab and evaluate.

hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE May 21, 1993

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

This space for State Use
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAY 24 1993

CONDITIONS OF APPROVAL, IF ANY:

48 FEB 1993

RECEIVED
MAY 24 1993
OCD HOBBS OFFICE