State of New Mexico Ene Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICTI

OIL CONSERVATION DIVISION

P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	ox 2088 30-025-32703	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2	5. Indicate Type of Lease STATE FEE KX	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	BACK TO A 7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL OAS WELL WELL OTHER	NOVEMBER 16	
2. Name of Operator	8. Well No.	
MARALO, INC. 3. Address of Operator	9. Pool name or Wildcat	
P. O. BOX 832, MIDLAND, TX 79702	WILDCAT (DEVONIAN)	
4. Well Location Unit Letter J: 2240 Feet From The SOUTH Lin	ne and 2310 Feet From The EAST Line	
Section 16 Township 13S Range 10. Elevation (Show whether DF, RKB, II 3820' GR	38E NMPM LEA County RT, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of	of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED	IAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMME	ENCE DRILLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING CASING	TEST AND CEMENT JOB	
OTHER:OTHER	:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pert work) SEE RULE 1103.	inent dates, including estimated date of starting any proposed	
RU plugging unit. RIH with 5 1/2" CIBP on wireline. Set @ ± 12,325'. Cap C	IBP w/35' cement.	
2. PU workstring. RIH. Circ hole w/10# per gallon mud laden fluid with 25# gel	/bbl.	
3. POH w/tubing. RIH with casing cutters. Cut 5 1/2" 17# csg @ ± 10,320'. Cut, pull & LD 5 1/2" csg.		
4. RIH with tubing. Spot 100' cement plug across 5 1/2" casing stub, 50' in 50'		
5. PUH with tubing. Spot 100' cement plug across Glorieta 6050 - 6150'. Min 5	••	
6. PUH w/ tubing. Spot 130' cement plug across base of 8 5/8" and base of sa sxs.	lt 4520 - 4650'. Min 60	
.7. PUH with tubing. Spot 100' cement plug 400 - 500' across base 13 3/8". Mi	n 40 sxs.	
8. Set surface plug min 10 sxs. Install dry hole marker, clean location.		
Lhereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Devether Lagare TITLE REGUI	LATORY ANALYST DATE MARCH 26, 1997	
TYPEOR PRINT NAME DOROTHEA LOGAN	TELEPHONE NO. (915) 684-744	
(This space for State Use) ORIGINAL SIGNED BY	198 01 1397	
APPROVED BY GARY WINK TILE	DATE	

JU

CONDITIONS OF APPROVAL, IF ANY: