## Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Departme.

Form C-103 Revised 1-1-89

District Cities	OT CONCEDUATIO	N DIVISION		
STRICT I D. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-025-33275		
DISTRICT II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.	
			VA-0357	
( DO NOT USE THIS FORM FOR PE	FICES AND REPORTS ON WEL ROPOSALS TO DRILL OH TO DEEPEN RYOR. USE "APPLICATION FOR PER C-101) FOR SUCH PROPOSALS.)	OH PLUG BACK TO A	7. Lease Name or Unit Agreement	ı Name
1. Type of Well: OIL GAS WELL X WELL	OTHER		Papalotes Unit	
2. Name of Operator	DAMI ON		8. Well No.	
YATES PETROLEUM CORPORATION			9. Pool name or Wildcat	
3. Address of Operator 105 South 4th St., Artesia, NM 88210			Wildcat Morrow	
4. Well Location	960 Feet From The South	Line and330	Feet From TheEa	nst Line
	1/0	onge 34E	<b>ммрм</b> Lea	County
Section 34	Township 14S Ra		V//////	7///////
	4092'	GR		<u> </u>
	Appropriate Box to Indicate	Nature of Notice, R	leport, or Other Data	05
NOTICE OF IN	NTENTION TO:	SUE	BSEQUENT REPORT (	JF: 
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING C	CASING L
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN			G OPNS. PLUG AND	ABANDONMENT
PULL OR ALTER CASING CASING TEST AND C			EMENT JOB	
OTHER: OTHER: Product			ion casing & cement X	
12 Describe Proposed or Completed On	perations (Clearly state all pertinent details, a	and give pertinent dates, incl	luding estimated date of starting any p	proposed
TD 13660'. Reached follows: 76 joints N-80 LT&C (3388.62' 5-1/2" 17# 8rd L-80 shoe set at 13660'. Cemented in two sta of Super Flush 102 salt, .4% CFR3, .5% 4-14-96. Did not b Circulated through Premium H, 1/4#/sac 12.5). Tailed in w Bumped plug to 3000 Waiting on completi	TD at 7:00 AM 4-10-96.  of 5-1/2" 17# 8rd S-95 ); 46 joints of 5-1/2"  LT&C (5321.66') (Total Float collar set at 1: ges as follows: Stage ahead of 750 sacks Prem Halad 344 and .3% HR7 ump plug. Pumped calci DV tool for 4-1/4 hours k flocele, 5#/sack gils with 100 sacks "H" (yiel psi for 3 minutes, 0K. con unit.	Ran 334 joint LT&C (3080.88' 17# 8rd J-55 LT 13674.58') of 3615'. Externa 1: 500 gallons ium H silicate, (yield 1.67, we um displacement . Stage 2: 10 onite, .4% Hala d 1.18, weight WOC. Release	s of 5-1/2" 17# casi ); 81 joints of 5-1/ &C (1883.42'); 131 j casing set at 13660' al sleeve DV tool at mud flush and 500 g 5#/sack gilsonite, eight 13.0). PD 12:4 c - no bump. Shut do 050 sacks Halliburtor ad 322 (yield 1.94, v 15.6). PD 7:45 AM 4- Clerk DATE —	ing as /2" 17# 8rd joints of '. Float 10031'. gallons 1#/sack 45 AM own. n Lite weight 4-14-9614-96.
TYPE OR PRINT NAME   Rusty K1	ein		TELEPHO	NE NO. 505/748-
(This space for State Line) CHNAL SIG	NED BY JERRY SEXTON		A	PR 18 1996

\_\_\_ TITLE ---

APPROVED BY---

DISTRICT I SUPERVISOR