Submit 3 Copies to Appropriate
District Office

State of New Mexico Energy, anerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

WELL API NO.

S. INDICATE Type of Data STATE FE	F.O. Box 1980, 110008, 14141 80240		P.O. Box 2088 Santa Fe, New Mexico 87504-2088			30-025-3392	2	
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS	DISTRICT II P.O. Drawer DD, Artesia, NM 88210				5. Indic	ate Type of Lease	K FEE	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE 'APPLICATION FOR FERMIT' (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:	DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410					6. State Oil & Gas Lease No.		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE 'APPLICATION FOR FERMIT' (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A							
1. Type of Well: Other						7. Lease Name or Unit Agreement Name		
1. Type of Well 1. Name of Operator 2. Name of Operator 2. Name of Operator 3. Address of Operator 50.8 W. Wall, Ste. 100 Midland, TX. 79701 9. Pool name or Wildcat 50.8 W. Wall, Ste. 100 Midland, TX. 79701 Wildcat (Atoka) 4. Well Location 1. Unit Letter G 2. 2040 Feet From The North Line and 2.040 Feet From The East Line Section 27 Township 14-S Range 34-E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. X PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: The County Th		(FORM C-101) F	OR SUCH PROPOSALS.)		——————————————————————————————————————	stacado 27 :	State	
2 Name of Operator Rand Paulson Oil Company, Inc. 3. Address of Operator 508 W. Wall, Ste. 100 Midland, TX. 79701 Wildcat (Atoka) 4. Well Location Unit Letter G: 2040 Feet From The North Line and 2040 Feet From The East Line Section 27 Township 14-S Range 34-E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR. etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent datails, and give perinent data; including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30 PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cemented with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT ³ /sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole @ 10,713'.	OIL —	GAS WELL K.	OTHER.			beacado 27	beace	
Rand Paulson Oil Company, IRC. 3. Address of Operator 508 W. Wall, Ste. 100 Midland, TX. 79701 Wildcat 4. Well Location Unit Letter G: 2040 Feet From The North Line and 2040 Feet From The East Line Section 27 Township 14-S Range 34-E NMPM Lea County 10. Elevation (Show Watcher DF, RKB, KT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30 PM. Drill 17 1/2" hole to 403' and set 13.3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT ² /sk. Followed by 200 sx C Neat. Dv tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WoC. Install well head and BOP. Test to 1000 psi. Drill 17 7/8" hole @ 10,713'.					8. Well	No.		
3. Address of Operator 508 W. Wall, Ste. 100 Midland, TX. 79701 Wildcat 4. Well Location Unit Letter G: 2040 Feet From The North Line and 2040 Feet From The East Line Section 27 Township 14-S Range 34-E NMFM Lea County 10. Elevation (Show whather DF, RKB, KT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON GHANGE PLANS GCAMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent datalls, and give pertinent datas, including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30 PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 min0K. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT 3/sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole. 5-13-97 Drilling 7 7/8" hole @ 10,713'.	•	Paulson Oil	Company, Inc	•		2		
Solid W. Wall, Ste. 100 Midland, TX. 79701 Wildcat (Atoka)						9. Pool name or Wildcat		
Well Location Unit Letter G : 2040 Feet From The North Line and 2040 Feet From The East Line Section 27 Township 14-S Range 34-E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.)	-	. Wall. Ste.	. 100 Midla	nd. TX. 797	01	Wildcat (Atoka)	
Unit Letter G : 2040 Peet From The North Line and 2040 Feet From The East Line Section 27 Township 14-S Range 34-E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent date, including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt & 12.4 #/gal and 2.14 FT ³ /sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole @ 10,713'.		. warry boo	112424	,	 	,		
10. Elevation (Show whather DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30 PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT³/sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole. 5-13-97 Drilling 7 7/8" hole @ 10,713'.		G : 2040 Fe	set From The North	Line and	2040	Feet From The Eas	t Line	
10. Elevation (Show whather DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30 PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT³/sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole. 5-13-97 Drilling 7 7/8" hole @ 10,713'.		.7	11-C	B 34-F	NIMEDA	T.e.a	County	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT²/sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole. 5-13-97 Drilling 7 7/8" hole.	Section 4	. , ////////////////////////////////////	10. Elevation (Show wh	ether DF, RKB, RT, GR. e		7//////	//////////////////////////////////////	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30 PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL 2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8". 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT /sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole. 5-13-97 Drilling 7 7/8" hole @ 10,713'.								
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30 PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL 2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8". 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT /sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole. 5-13-97 Drilling 7 7/8" hole @ 10,713'.		Charle Ameri	minto Don to India	ote Noture of Noti	ce Penort o	or Other Data		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. X PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: OTHER: OTHER: OTHER:								
COMMENCE DRILLING OPNS. X PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT 3/sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole. 5-13-97 Drilling 7 7/8" hole @ 10,713'.	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT³/sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole. 5-13-97 Drilling 7 7/8" hole @ 10,713'.	PERFORM REMEDIAL	WORK	PLUG AND ABANDON	REMEDIAL WO	RK	ALTERING (CASING	
OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT 3/sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole. 5-13-97 Drilling 7 7/8" hole @ 10,713'.	TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. X PLUG AND ABANDONMENT							
12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 4-8-97 Spud well @ 5:30PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT /sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole. 5-13-97 Drilling 7 7/8" hole @ 10,713'.	PULL OR ALTER CASING CASING TEST AND CEMENT JOB							
4-8-97 Spud well @ 5:30PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT /sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole. 5-13-97 Drilling 7 7/8" hole @ 10,713'.	OTHER:			OTHER:				
4-8-97 Spud well @ 5:30PM. Drill 17 1/2" hole to 403' and set 13 3'8" 54.5 lbs. J-55 STC casing. Cemented with 500 sx Class C + 2% CACL2. Circ. 40 sx to surf. Install casing head and BOP. Test to 1000 psi-30 minOK. Drill 11" hole to 6180'. Set 8 5/8" 32 lbs. J-55 & N-80 STC casing. Cement with 625 sx C + 6% gel + 5% salt @ 12.4 #/gal and 2.14 FT /sk. Followed by 200 sx C Neat. DV tool @ 4068'. Cemented with 1550 sx Class C + 3% SMS + 3#/sk salt. Followed with 200 sx C Neat. Circ. 286 sx to surface. WOC. Install well head and BOP. Test to 1000 psi. Drill 7 7/8" hole. 5-13-97 Drilling 7 7/8" hole @ 10,713'.			learly state all pertinent deta	sils, and give pertinent date	es, including estim	ated date of starting any p	proposed	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		54.5 lbs. Journal of CACL2. Circle to 1000 pside 32 lbs. J-58 + 58 salt @ Neat. DV to SMS + 3#/sk to surface. psi. Drill	-55 STC casin c. 40 sx to s -30 minOK. 5 & N-80 STC 12.4 #/gal a ool @ 4068'. salt. Follo WOC. Insta 7 7/8" hole.	g. Cemented urf. Instal Drill 11" h casing. Cem nd 2.14 FT / Cemented wiwed with 200 11 well head	N with 50 Il casing nole to 6 ment with /sk. Fol Ith 1550) sx C Ne	0 sx Class head and B 180'. Set 625 sx C + lowed by 20 sx Class C eat. Circ.	C + 2% OP. Test 8 5/8" 6% gel 0 sx C + 3% 286 sx	
// PPR / N. F	I hereby certify that the in	formation above is true and co	mplete to the best of my knowled	lge and belief.				

DATE 5 - 13 - 97_ mu ___Agent Willend SIGNATURE TELEPHONE NO. 915-687-0323 O. H. Routh TYPE OR PRINT NAME Orig. Signed by Paul Kautz (This space for State Use) MAY 1 9 1997 60 N8 185 DATE APPROVED BY -