to Appropriate Energy, Aerals and Natural Resources Departm District Office	Form C-103 Revised 1-1-89
DISTRICT I OIL CONSERVATION DIVISION	
P. O. Box 1980, Hobbs, NM 88240 2040 South Pacheco Santa Fe, New Mexico 86595	WELL API NO. 30-025-34491
DISTRICT II	5. Indicate Type of Lease
P. O. Drawer DD, Artesia, NM 88210	STATE X FEE
1. O. Dianci DD, Altesia, Itik Codito	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No. V-4190-3
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT	
(FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well:	
Oil Gas	
Well 🚺 Well 🗌 OTHER	
2. Name of Operator	8. Well No.
-	
TMBR/Sharp Drilling, Inc.	1 0. Pool nome on Wildoot
3. Address of Operator	9. Pool name or Wildcat
P. O. Drawer 10970, Midland, TX 79702	Wildcat; Upper Penn
4. Well Location	
Unit Letter <u>A</u> : <u>330</u> Feet From The <u>North</u> Line and	330 Feet From The East
	MPM County Lea
10. Elevation (Show whether DF, RKB, RT, GI	R, etc.)
4005' GR 11. Check Appropriate Box to Indicate Nature of Notice, Rep	nort or Other Date
•••••	port, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	Ing opns. Plug and abandon X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND	Ing opns. Plug and abandon X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	Ing opns. Plug and abandon X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND CASING TEST AND OTHER: OTHER: OTHER: OTHER:	ALTERING CASING Indicating casing LING OPNS. PLUG AND ABANDON X CEMENT JOB Indicating casing Indicating casing
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includiwork) SEE RULE 1103.	ALTERING CASING Indicating casing LING OPNS. PLUG AND ABANDON X CEMENT JOB Indicating Indicating
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND OTHER: OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includit work) SEE RULE 1103. 09/26/98 Set Plugs to P&A well as follows:	ALTERING CASING ALTERING ALTERING CASING ALTERING CASING ALTERING ALT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND OTHER: OTHER: OTHER: OTHER: Plug #1 11,100 - 11,000' 30 sx Cl H Plug #	ALTERING CASING LING OPNS. PLUG AND ABANDON CEMENT JOB ing estimated date of starting any proposed 49 2,290 - 2,190' 50 sx Cl C
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND CASING TEST AND OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includit work) SEE RULE 1103. O9/26/98 Set Plugs to P&A well as follows: Plug #1 11,100 - 11,000' 30 sx Cl H Plug # Plug #2 10,874 - 10,774' 30 sx Cl H Plug #	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND CASING TEST AND OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includit work) SEE RULE 1103. O9/26/98 Set Plugs to P&A well as follows: Plug #1 11,100 - 11,000' 30 sx Cl H Plug # Plug #3 10,680 - 10,580' 30 sx Cl H Plug #	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND CASING TEST AND OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includi work) SEE RULE 1103. OTHER: Plug #1 09/26/98 Set Plugs to P&A well as follows: Plug #1 11,100 - 11,000' 30 sx Cl H Plug # Plug #2 10,874 - 10,774' 30 sx Cl H Plug # Plug # Plug #4 10,340 - 10,240' 30 sx Cl H Plug #	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND CASING TEST AND OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includi work) SEE RULE 1103. O9/26/98 Set Plugs to P&A well as follows: Plug #1 11,100 - 11,000' 30 sx Cl H Plug # Plug #2 10,874 - 10,774' 30 sx Cl H Plug # Plug #3 10,680 - 10,580' 30 sx Cl H Plug # Plug #4 10,340 - 10,240' 30 sx Cl H Plug #	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND CASING TEST AND OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includi work) SEE RULE 1103. O9/26/98 Set Plugs to P&A well as follows: Plug #1 11,100 - 11,000' 30 sx Cl H Plug # Plug #2 10,874 - 10,774' 30 sx Cl H Plug # Plug #3 10,680 - 10,240' 30 sx Cl H Plug # Plug #4 10,340 - 10,240' 30 sx Cl H Plug # Plug #6 8,000 - 7,900' 30 sx Cl H Plug #	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND OTHER: OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includiwork) SEE RULE 1103. O9/26/98 Set Plugs to P&A well as follows: Plug #1 11,100 - 11,000' 30 sx Cl H Plug # Plug #2 10,874 - 10,774' 30 sx Cl H Plug # Plug #3 10,680 - 10,580' 30 sx Cl H Plug # Plug #4 10,340 - 10,240' 30 sx Cl H Plug # Plug #5 9,570 - 9,470' 30 sx Cl H Plug # Plug #6 8,000 - 7,900' 30 sx Cl H Plug # Plug #7 5,950 - 5,850' 30 sx Cl H Plug #	ALTERING CASING ALING OPNS. PLUG AND ABANDON CLING OPNS. PLUG AND ABANDON CLICATION CONTRACTOR OF CONTRACT ON CONTRACT OF CONT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND CASING TEST AND OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includi work) SEE RULE 1103. O9/26/98 Set Plugs to P&A well as follows: Plug #1 11,100 - 11,000' 30 sx Cl H Plug # Plug #2 10,874 - 10,774' 30 sx Cl H Plug # Plug #3 10,680 - 10,240' 30 sx Cl H Plug # Plug #4 10,340 - 10,240' 30 sx Cl H Plug # Plug #6 8,000 - 7,900' 30 sx Cl H Plug #	ALTERING CASING ALING OPNS. PLUG AND ABANDON CLING OPNS. PLUG AND ABANDON CLICATION CONTRACTOR OF CONTRACT ON CONTRACT OF CONT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includiwork) SEE RULE 1103. OTHER: DTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includiwork) SEE RULE 1103. OTHER: Plug #1 13. 09/26/98 Set Plugs to P&A well as follows: Plug #1 Plug #2 10,874 - 10,774' 14. Plug #2 10,874 - 10,774' 30 sx Cl H Plug # 10. 9/26/98 Set Plugs to P&A well as follows: Plug #3 10,680 - 10,580' 10. 9/26/98 Set Plugs to P&A well as follows: Plug #2 10,874 - 10,774' 30 sx Cl H Plug #3 10,680 - 10,240' 30 sx Cl H Plug # Plug # Plug #4 10,340 - 10,240' 30 sx Cl H Plug # Plug #6 8,000 - 7,900' 30 sx Cl H Plug # Plug #8 4,550 - 5,850' 30 sx Cl C + CaCl, WOC 4 hrs & top	ALTERING CASING ALING OPNS. PLUG AND ABANDON CLING OPNS. PLUG AND ABANDON CLICATION CONTRACTOR OF CONTRACT ON CONTRACT OF CONT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND OTHER: OTHER: OTHER: OTHER: OTHER: OTHER: Image: Completed Operations (Clearly state all pertinent details, and give pertinent dates, includivers) SEE RULE 1103. 09/26/98 Set Plugs to P&A well as follows: Plug #1 11,100 - 11,000' 30 sx Cl H Plug # Plug #2 10,874 - 10,774' 30 sx Cl H Plug # Plug # Plug # Plug #3 10,680 - 10,580' 30 sx Cl H Plug # Plug # Plug #4 10,340 - 10,240' 30 sx Cl H Plug # Plug #5 9,570 - 9,470' 30 sx Cl H Plug # Plug #6 8,000 - 7,900' 30 sx Cl H Plug # Plug #7 5,950 - 5,850' 30 sx Cl H Plug #	ALTERING CASING ALTERING OPNS. PLUG AND ABANDON X CEMENT JOB CEMENT JOB CEMEN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND CASING TEST AND OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includi work) SEE RULE 1103. OTHER: Plug #1 09/26/98 Set Plugs to P&A well as follows: Plug #1 Plug #2 10,874 - 10,774' 30 sx Cl H Plug # Plug #2 10,874 - 10,774' 30 sx Cl H Plug # Plug # Plug #3 10,680 - 10,580' 30 sx Cl H Plug # Plug #4 10,340 - 10,240' 30 sx Cl H Plug # Plug #5 9,570 - 9,470' 30 sx Cl H Plug # Plug #6 8,000 - 7,900' 30 sx Cl H Plug # Plug #8 4,550 - 4,450' 50 sx Cl C + CaCl, WOC 4 hrs & to	ALTERING CASING ALTERING OPNS. PLUG AND ABANDON X CEMENT JOB CEMENT JOB CEMEN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND CASING TEST AND OTHER:	ALTERING CASING LING OPNS. PLUG AND ABANDON CEMENT JOB ing estimated date of starting any proposed 49 2,290 - 2,190' 50 sx Cl C 40 50 sx Cl C 41 30 - Surface 10 sx Cl C tag @ 4,425'. 10 sx Cl C tag @ 4,425'. 12 tag @ 1,425'. 13 tag @ 1,425'. 13 tag @ 1,425'. 13
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND CASING TEST AND OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includi work) SEE RULE 1103. 09/26/98 Set Plugs to P&A well as follows: Plug #1 11,100 - 11,000' 30 sx Cl H Plug # Plug #1 11,100 - 11,000' 30 sx Cl H Plug # Plug # Plug # Plug #1 10,874 - 10,774' 30 sx Cl H Plug # Plug # Plug #3 10,680 - 10,580' 30 sx Cl H Plug # Plug #4 10,340 - 10,240' 30 sx Cl H Plug # Plug #5 9,570 - 9,470' 30 sx Cl H Plug # Plug #6 8,000 - 7,900' 30 sx Cl H Plug # Plug #8 4,550 - 4,450' 50 sx Cl C + CaCl, WOC 4 hrs & total well well well well well well well we	ALTERING CASING LING OPNS. PLUG AND ABANDON CEMENT JOB Cing estimated date of starting any proposed 49 2,290 - 2,190' 50 sx Cl C 40 50 sx Cl C 41 30 - Surface 10 sx Cl C 411 30 - Surface 10 sx Cl C 42 4,425'. 10 sx Cl C 43 10 sx Cl C 10 sx Cl C 44 10 sx Cl C 10 sx Cl C 45 10 sx Cl C 10 sx Cl C 46 10 sx Cl C 10 sx Cl C 47 10 sx Cl C 10 sx Cl C 47 10 sx Cl C 10 sx Cl C 47 10 sx Cl C 10 sx Cl C 48 10 sx Cl C 10 sx Cl C 41 10 sx Cl C 10 sx Cl C 41 10 sx Cl C 10 sx Cl C 41 10 sx Cl C 10 sx Cl C 41 10 sx Cl C 10 sx Cl C 41 10 sx Cl C 10 sx Cl C 41 10 sx Cl C 10 sx Cl C 41 10 sx Cl C 10 sx Cl C 41 </td
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING TEST AND OTHER: OTHER: 00THER: OTHER: OTHER: OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includi work) SEE RULE 1103. OTHER: Image: Distribution of the state of	ALTERING CASING LING OPNS. PLUG AND ABANDON CEMENT JOB ing estimated date of starting any proposed 49 2,290 - 2,190' 50 sx Cl C 40 50 sx Cl C 41 30 - Surface 10 sx Cl C 41 30 - Surface 10 sx Cl C 42 10 sx Cl C 10 sx Cl C 43 10 sx Cl C 10 sx Cl C 44 10 sx Cl C 10 sx Cl C 44 10 sx Cl C 10 sx Cl C 44 10 sx Cl C 10 sx Cl C 44 10 sx Cl C 10 sx Cl C 44 10 sx Cl C 10 sx Cl C 44 10 sx Cl C 10 sx Cl C 44 10 sx Cl C 10 sx Cl C 45 10 sx Cl C 10 sx Cl C 46 10 sx Cl C 10 sx Cl C 47 10 sx Cl C 10 sx Cl C 48 10 sx Cl C 10 sx Cl C 49 10 sx Cl C 10 sx Cl C 40 10 sx Cl C 10 sx Cl C 40 10 sx Cl C 10 sx Cl C