District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505  Energy, Minerals and Natural Resources  Revised March 25, 1 WELL API NO. 30-025-35937  5. Indicate Type of Lease STATE FEE 6  6. State Oil & Gas Lease No.	Submit 3 Copies To Appropriate District Office	State of New 1	Mexico	Form C-103
District	District I	Energy, Minerals and Natural Resources		Revised March 25, 1999
1301 W. Grand Ave., Artesia, NM 88210   1220 South St. Francis Dr.   122				
District IV   District IV   Santa Fe, NM 87505   STATE   FEE     fo. State Oil & Gas Lease No.		OIL CONSERVATION DIVISION		
Santa Fe, NM 87505   6. State Oil & Gas Lease No.		1220 South St. Francis Dr.		
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:   Gas Well   Other   Burrus    2. Name of Operator Ricks Exploration, Inc.   6  3. Address of Operator   9. Pool name or Wildcat    2.10 Park Ave, Ste 3000, Oklahoma City, OK 73102   7. Lease Name or Unit Agreement Name of Well No.    4. Well Location   9. Pool name or Wildcat   7. Trinity; Wolfcamp    4. Well Location   Unit Letter_N   330'   feet from the South   Ine and 2310'   feet from the West   Ine    Section 22   Township 128   Range 38E   NMPM   County   Lea    10. Elevation (Show whether DR, RKB, RT, GR, etc.)   3801' GL, 3819' KB, 3818' DF    11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data   NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:    PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    CASING TEST AND   CASING TEST AND   CEMENT JOB    OTHER:   OTHER: Completion   CASING TEST AND   CEMENT JOB   CASING TEST AND   CEMENT JOB    OTHER:   OTHER: Completion   CASING TEST AND   CEMENT JOB   CASING TEST AND   CASING TEST AND   CEMENT JOB   CASING TEST AND		Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well: Oil Well   Gas Well   Other	1220 S. St. Francis Dr., Santa Fe, NM			
Unit Letter_N : 330'feet from theSouth line and2310'feet from theWest line  Section 22	SUNDRY NOTION  (DO NOT USE THIS FORM FOR PROPOSALS.)  1. Type of Well: Oil Well Gas Well  2. Name of Operator Ricks Exploration, Inc.  3. Address of Operator 210 Park Ave, Ste 3000, Oklahoma (1)	ALS TO DRILL OR TO DEEPEN OR ATION FOR PERMIT" (FORM C-101) Other	PLUG BACK TO A ) FOR SUCH  I  8	8. Well No. 6. Pool name or Wildcat
Section 22  Township 12S Range 38E NMPM County Lea  10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3801' GL, 3819' KB, 3818' DF  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS.  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER: OTHER: Completion  72. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dates starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  8/13/02- MIRU. Tagged @ 9220'. Circ hole w/22 bbls 2% KCL. Spot 4 bbls 90/10 15% HCl from 9100'-8920'. 8/14/02- Ran CBL/GR/CCL log. TOC @ 2440'. Perf Wolfcamp w/4" pred csg gun w/2 JSPF from 9035'-9087'. RIH w/jts, pkr, SN tbg. Set pkr @ 8873'. Test BOP & pkr to 1500 psi-Ok. Swab well.				
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3801' GL, 3819' KB, 3818' DF  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND PULL OR ALTER CASING MULTIPLE CASING TEST AND OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  8/13/02- MIRU. Tagged @ 9220'. Circ hole w/22 bbls 2% KCL. Spot 4 bbls 90/10 15% HCl from 9100'-8920'. 8/14/02- Ran CBL/GR/CCL log. TOC @ 2440'. Perf Wolfcamp w/4" pred csg gun w/2 JSPF from 9035'-9087'. RIH_w/jts, pkr, SN tbg. Set pkr @ 8873'. Test BOP & pkr to 1500 psi-Ok. Swab well.	Unit LetterN:330	)'feet from theSouth	line and2310'_	feet from theWestline
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3801' GL, 3819' KB, 3818' DF  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND PULL OR ALTER CASING MULTIPLE CASING TEST AND OTHER:  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  8/13/02- MIRU. Tagged @ 9220'. Circ hole w/22 bbls 2% KCL. Spot 4 bbls 90/10 15% HCl from 9100'-8920'. 8/14/02- Ran CBL/GR/CCL log. TOC @ 2440'. Perf Wolfcamp w/4" pred csg gun w/2 JSPF from 9035'-9087'. RIH_w/jts, pkr, SN tbg. Set pkr @ 8873'. Test BOP & pkr to 1500 psi-Ok. Swab well.	Section 22	Township 12S Re	ange 38F N	MPM County Lea
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER: OTHER: Completion  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  8/13/02- MIRU. Tagged @ 9220'. Circ hole w/22 bbls 2% KCL. Spot 4 bbls 90/10 15% HCl from 9100'-8920'.  8/14/02- Ran CBL/GR/CCL log. TOC @ 2440'. Perf Wolfcamp w/4" pred csg gun w/2 JSPF from 9035'-9087'. RIH w/jts, pkr, SN tbg. Set pkr @ 8873'. Test BOP & pkr to 1500 psi-Ok. Swab well.	Beetlen 22		DR, RKB, RT, GR, etc.)	Wil Wi County Lea
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. ALTERING CASING  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ABANDONMENT  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER: OTHER: OTHER: Completion  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  8/13/02- MIRU. Tagged @ 9220'. Circ hole w/22 bbls 2% KCL. Spot 4 bbls 90/10 15% HCl from 9100'-8920'.  8/14/02- Ran CBL/GR/CCL log. TOC @ 2440'. Perf Wolfcamp w/4" pred csg gun w/2 JSPF from 9035'-9087'. RIH w/jts, pkr, SN tbg. Set pkr @ 8873'. Test BOP & pkr to 1500 psi-Ok. Swab well.	; ;	3801' GL, 3819' KB, 3818' DI	F	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB  OTHER: OTHER: Completion  12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  8/13/02- MIRU. Tagged @ 9220'. Circ hole w/22 bbls 2% KCL. Spot 4 bbls 90/10 15% HCl from 9100'-8920'.  8/14/02- Ran CBL/GR/CCL log. TOC @ 2440'. Perf Wolfcamp w/4" pred csg gun w/2 JSPF from 9035'-9087'. RIH w/jts, pkr, SN tbg. Set pkr @ 8873'. Test BOP & pkr to 1500 psi-Ok. Swab well.				
TEMPORARILY ABANDON			<b>I</b>	
PULL OR ALTER CASING	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING CASING ☐
PULL OR ALTER CASING    MULTIPLE    COMPLETION    OTHER: Completion    OTHER: Completion    OTHER: Completion    12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  8/13/02- MIRU. Tagged @ 9220'. Circ hole w/22 bbls 2% KCL. Spot 4 bbls 90/10 15% HCl from 9100'-8920'.  8/14/02- Ran CBL/GR/CCL log. TOC @ 2440'. Perf Wolfcamp w/4" pred csg gun w/2 JSPF from 9035'-9087'. RIH w/its, pkr, SN tbg. Set pkr @ 8873'. Test BOP & pkr to 1500 psi-Ok. Swab well.	TEMPORARILY ABANDON	CHANGE PLANS		
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.</li> <li>8/13/02- MIRU. Tagged @ 9220'. Circ hole w/22 bbls 2% KCL. Spot 4 bbls 90/10 15% HCl from 9100'-8920'.</li> <li>8/14/02- Ran CBL/GR/CCL log. TOC @ 2440'. Perf Wolfcamp w/4" pred csg gun w/2 JSPF from 9035'-9087'. RIH w/its, pkr, SN tbg. Set pkr @ 8873'. Test BOP &amp; pkr to 1500 psi-Ok. Swab well.</li> </ol>		<u> </u>	CASING TEST AND	
<ul> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.</li> <li>8/13/02- MIRU. Tagged @ 9220'. Circ hole w/22 bbls 2% KCL. Spot 4 bbls 90/10 15% HCl from 9100'-8920'.</li> <li>8/14/02- Ran CBL/GR/CCL log. TOC @ 2440'. Perf Wolfcamp w/4" pred csg gun w/2 JSPF from 9035'-9087'. RIH w/its, pkr, SN tbg. Set pkr @ 8873'. Test BOP &amp; pkr to 1500 psi-Ok. Swab well.</li> </ul>	OTHER:		OTHER: Completion	. Fr
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  8/13/02- MIRU. Tagged @ 9220'. Circ hole w/22 bbls 2% KCL. Spot 4 bbls 90/10 15% HCl from 9100'-8920'.  8/14/02- Ran CBL/GR/CCL log. TOC @ 2440'. Perf Wolfcamp w/4" pred csg gun w/2 JSPF from 9035'-9087'. RIH w/its, pkr, SN tbg. Set pkr @ 8873'. Test BOP & pkr to 1500 psi-Ok. Swab well.	12. Describe proposed or completed		·	
8/14/02- Ran CBL/GR/CCL log. TOC @ 2440'. Perf Wolfcamp w/4" pred csg gun w/2 JSPF from 9035'-9087'. RIH w/jts, pkr, SN tbg. Set pkr @ 8873'. Test BOP & pkr to 1500 psi-Ok. Swab well.	starting any proposed work). SEE	RULE 1103. For Multiple Co	mpletions: Attach wellb	ore diagram of proposed completion or
8/16/02- Acidize Wolfcamp perfs from 9035'-9087' w/5200 gals 90/10 HCl dropping 150 BS. Swab & shut well in. 8/19/02- Swab & release pkr. 8/21/02- Ran tbg & set @ 9211' w/mech SN @ 9178'. ND BOP. Set TAC @ 8848' in 14,000# tension Ran pmp & rods. RD & rls	8/14/02- Ran CBL/GR/CCL log. TOO tbg. Set pkr @ 8873'. Test E 8/15/02- Swab well. 8/16/02- Acidize Wolfcamp perfs from 8/19/02- Swab & release pkr.	C @ 2440'. Perf Wolfcamp w/4 BOP & pkr to 1500 psi-Ok. Swa n 9035'-9087' w/5200 gals 90/1	" pred csg gun w/2 JSPF ab well. 0 HCl dropping 150 BS.	Swab & shut well in.  # tensions Ran pmp & rods. RD & rls rig.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	I hereby certify that the information ab	ove is true and complete to the	best of my knowledge ar	nd belief.
SIGNATURE Loru Bustamanto TITLE Production Analyst DATE 8/28/02	SIGNATURE LOVA BUSTA	mark TITLE	Production Analyst	DATE8/28/02
Type or print name Dora Bustamante Telephone No. (915) 683-7443	Type or print name Dora Bustamante			Telephone No. (915) 683-7443
(This space for State use)  ORIGINAL SIGNED BY  SEP 1 1 2000	(This space for State use)		ORIGINAL SIGNED	CED 4 4 2000
PAIR F KAREZ	A DDDD OVED DV	mini n	PAUL F. KAUTZ	OLI I I ZUUZ
APPPROVED BY TITLE PROCESS DATE  Conditions of approval, if any:  DATE		TITLE	– – .	DATE

:5 C S