

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Silver Monument Minerals, Inc.</b>		8. Farm or Lease Name <b>Atlantic Tucker</b>
3. Address of Operator <b>Box 1476, Lovington, New Mexico 88260</b>		9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>I</b> , <b>660'</b> FEET FROM THE <b>East</b> LINE AND <b>1980</b> FEET FROM THE <b>South</b> LINE, SECTION <b>23</b> TOWNSHIP <b>7 South</b> RANGE <b>32 East</b> NMPM.		10. Field and Pool, or Wildcat <b>Chaveroo</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4462.2 KB</b>		12. County <b>Roosevelt</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Pull Tubing, Rods & Pump, Remove well head, all fittings, valves and connections and pull approximately 2500' of 5½" casing, and plug as follows:**

**CIBP topped with 5 sx cement at 3500'.  
25 sx cement on top of stub at 2500'.  
28 sx top of salt 1780' to 1880'.  
28 sx bottom of surface 347'.  
10 sx surface with marker.  
9.5 mud between plugs.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *John E. Brown* TITLE **President** DATE **3/19/74**

APPROVED BY *John E. Brown* TITLE  DATE   
CONDITIONS OF APPROVAL, IF ANY: